

CONDITION CHECK REPORT

BG No.	PC7538387	CHASSIS No.	Y12-132111	DATE	2019 / 10 / 13
--------	-----------	-------------	------------	------	----------------

1	TIMING BELT CHANGE		YES		KM	13	POWER WINDOW (R FRONT)	(OK)	NG				NONE					
2	COOLANT LEVEL	(OK)	NG	LEAK			14 POWER WINDOW (L FRONT)	(OK)	NG				NONE					
3	ENGINE OIL LEVEL	(OK)	NG	DIRT			15 POWER WINDOW (R REAR)	(OK)	NG				NONE					
4	OIL LEAKING	(OK)	NG	SMALL	BIG		16 POWER WINDOW (L REAR)	(OK)	NG				NONE					
5	TIRE (R FRONT)	(OK)	NG	185/65R15		RFT	17 A/C CONDITION	(OK)	NG	WIND BLOWS OK	CAN'T OPERATE	A/C NONE						
6	TIRE (L FRONT)	(OK)	NG			R	18 INTERIOR CONDITION	OK	(NG)	(DIRT)	SMOKING SMELL	OTHER SMELL						
7	TIRE (R REAR)	(OK)	NG			R	19 CHECK / WARNING LAMP	(OK)	E/G	ABS	AIRBAG	OTHER						
8	TIRE (L REAR)	(OK)	NG			R	(COMMENT) 18. 室内汚れ ハンドレストレハライザー					TESTER CHECK						
9	ENGINE NOISE	(OK)	NG	E/G	OTHERS													
10	ENGINE CONDITION	(OK)	NG	IDLING	SMOKE													
11	EXHAUST LEAK	(OK)	NG	MUFFLER RUSTY	MISSING PARTS													
12	TRANSMISSION (AT / MT)	(OK)	NG	SHOCK	NOISE	SLIP												
OPTION																		
(RADIO)		(CD)		DVD		SUN ROOF						FLIP DOWN MONITOR						
REAR MONITOR		BACK CAMERA		CRUISE CONTROL		POWER SLIDING DOOR (LEFT)		POWER SLIDING DOOR (RIGHT)										
POWER BACK DOOR																		
(注意) オプション品が付いていて作動するのは「○」、付いていて作動しないものは「×」、オプション品が付いていないものは「無印」をお願いします。							(注意) NGが入った項目は、窓ガラスに記載せずコメントにすべて記載をお願いします。オークションシートをチェックして、U3-B3以上の凹みキズ、フロントガラスの割れやヒビ(マーカで囲んで)、その他目立つ破損部分があった場合は、写真撮影をお願いします。											

YARD	ECL木更津	INSPECTER	2. 井ノ木	AA SHEET	○
------	--------	-----------	--------	----------	---