

CONDITION CHECK REPORT

BH No.	178020	CHASSIS No.	HV37 - 209036
--------	--------	-------------	---------------

DATE : 2020 / 4 / 3

No.	Item	Status	TIRE			13	POWER WINDOW (R FRONT)	Status	14	POWER WINDOW (L FRONT)	Status	WIND					
			Size	Pressure	Direction							Blows	Operate	A/C			
1	TIMING BELT CHANGE	YES					OK	NG						NONE			
2	COOLANT LEVEL	OK	LEAK				OK	NG						NONE			
3	ENGINE OIL LEVEL	OK	DIRT				OK	NG						NONE			
4	OIL LEAKING	OK	SMALL	BIG			OK	NG						NONE			
5	TIRE (R FRONT)	OK	225/55 R17	RFT			OK	NG				WIND BLOWS OK	CAN'T OPERATE	A/C NONE			
6	TIRE (L FRONT)	OK	/ R	RFT			OK	NG				DIRT	SMOKING SMELL	OTHER SMELL			
7	TIRE (R REAR)	OK	/ R	RFT			OK	E/G				ABS	AIRBAG	OTHER			
8	TIRE (L REAR)	OK	/ R	RFT													
9	ENGINE NOISE	OK	E/G	OTHERS		<p style="font-size: 1.2em; font-weight: bold;">HYBRID!</p> <p>エンジン音は正常です。</p> <p>ブレーキ音は正常です。</p> <p>変速機音は正常です。</p> <p>その他目立つ破損部分はありません。</p>											
10	ENGINE CONDITION	OK	IDLING	SMOKE													
11	EXHAUST LEAK	OK	MUFFLER RUSTY	MISSING PARTS													
12	TRANSMISSION (AT/MT)	OK	SHOCK	NOISE	SLIP												
(COMMENT)																	
TESTER CHECK																	
OPTION																	
RADIO			SUN ROOF			FLIP DOWN MONITOR			CRUISE CONTROL			POWER SLIDING DOOR (LEFT)			POWER SLIDING DOOR (RIGHT)		
REAR MONITOR			BACK CAMERA														
POWER BACK DOOR																	

(注意) オプション品が付いていて作動するものは「○」、付いていて作動しないものは「×」、オプション品が付いていないものは「無印」をお願いします。

YARD	ECL 富津
------	--------

INSPECTER	[Signature]
-----------	-------------

AA SHEET	0
----------	---