

# CONDITION CHECK REPORT

BH No.	P/23/2	CHASSIS No.	K4F23-032527	DATE	2021/4/14
--------	--------	-------------	--------------	------	-----------

1	TIMING BELT CHANGE	YES	KM	13	POWER WINDOW (R FRONT)	OK	NG				NONE		
2	COOLANT LEVEL	OK	LEAK		14	POWER WINDOW (L FRONT)	OK	NG			NONE		
3	ENGINE OIL LEVEL	OK	DIRT		15	POWER WINDOW (R REAR)	OK	NG			NONE		
4	OIL LEAKING	OK	SMALL	BIG	16	POWER WINDOW (L REAR)	OK	NG			NONE		
5	TIRE (R FRONT)	OK	6.00R15	RFT	17	A/C CONDITION	OK	NG	WIND BLOWS OK	CAN'T OPERATE	A/C NONE		
6	TIRE (L FRONT)	OK	/ 1 R	RFT	18	INTERIOR CONDITION	OK	NG	DIRT	SMOKING SMELL	OTHER SMELL		
7	TIRE (R REAR)	OK	/ 155R12	RFT	19	CHECK / WARNING LAMP	OK	E/G	ABS	AIRBAG	OTHER		
8	TIRE (L REAR)	OK	/ 1 R	RFT	(COMMENT)  MT車  車内汚れ シート汚れ  オート不良 腐食車						TESTER CHECK		
9	ENGINE NOISE	OK	E/G	OTHERS									
10	ENGINE CONDITION	OK	IDLING	SMOKE									
11	EXHAUST LEAK	OK	MUFFLER RUSTY	MISSING PARTS									
12	TRANSMISSION (AT / MT)	OK	SHOCK	NOISE							SLIP		
OPTION													
<input checked="" type="checkbox"/>	RADIO	<input checked="" type="checkbox"/>	DVD	SUN ROOF							FLIP DOWN MONITOR		
<input checked="" type="checkbox"/>	REAR MONITOR	<input checked="" type="checkbox"/>	BACK CAMERA	CRUISE CONTROL							POWER SLIDING DOOR (LEFT)	POWER SLIDING DOOR (RIGHT)	
<input checked="" type="checkbox"/>	POWER BACK DOOR												

(注意) オプション品が付いていて作動するのは「○」、付いていて作動しないものは「×」、オプション品が付いていないものは「無印」でお願いします。

(注意) NGが入った項目は、窓ガラスに記載せずコメントにすべて記載をお願いします。オークションシートをチェックして、U3・B3以上の凹みキズ、フロントガラスの割れやヒビ(マーカーで囲んで)、その他目立つ破損部分があった場合は、写真撮影をお願いします。

YARD	ECL木更津	INSPECTER	イズミ	AA SHEET	0
------	--------	-----------	-----	----------	---