

# CONDITION CHECK REPORT

BH No.	922837	CHASSIS No.	PCP81-5053428
--------	--------	-------------	---------------

DATE **2020 / 4 / 2 /**

1	TIMING BELT CHANGE	YES	NO	KM	13	POWER WINDOW (R FRONT)	OK	NG	NONE
2	COOLANT LEVEL	OK	NG	LEAK		14	POWER WINDOW (L FRONT)	OK	NONE
3	ENGINE OIL LEVEL	OK	NG	DIRT		15	POWER WINDOW (R REAR)	OK	NONE
4	OIL LEAKING	OK	NG	SMALL	BIG	16	POWER WINDOW (L REAR)	OK	NONE
5	TIRE (R FRONT)	OK	NG	M570 19	RFT	17	A/C CONDITION	OK	WIND BLOWS OK CAN'T OPERATE A/C NONE
6	TIRE (L FRONT)	OK	NG		RFT	18	INTERIOR CONDITION	OK	NG DIRT SMOKING SMELL OTHER SMELL
7	TIRE (R REAR)	OK	NG		RFT	19	CHECK / WARNING LAMP	OK	E/G ABS AIRBAG OTHER
8	TIRE (L REAR)	OK	NG		RFT	(COMMENT) 922837 3737 3737			TESTER CHECK
9	ENGINE NOISE	OK	NG	E/G	OTHERS				
10	ENGINE CONDITION	OK	NG	IDLING	SMOKE				
11	EXHAUST LEAK	OK	NG	MUFFLER RUSTY	MISSING PARTS				
12	TRANSMISSION (AT / MT)	OK	NG	SHOCK	NOISE				SLIP
OPTION									
RADIO		CD		DVD		SUN ROOF		FLIP DOWN MONITOR	
REAR MONITOR		BACK CAMERA		CRUISE CONTROL		POWER SLIDING DOOR (LEFT)		POWER SLIDING DOOR (RIGHT)	
POWER BACK DOOR									
(注意) オプション品が付いていて作動するものは「○」、付いていて作動しないものは「×」、オプション品が付いていないものは「無印」でお願いします。									
(注意) NGが入った項目は、窓ガラスに記載せずコメントにすべて記載をお願いします。オークションシートをチェックして、U3-B3以上の凹みキズ、フロントガラスの割れやヒビ(マーカで囲んで)、その他目立つ破損部分があった場合は、写真撮影をお願いします。									

YARD **ECL木更津**

INSPECTER **木**

AA SHEET **2**