

CONDITION CHECK REPORT

BH No.	939 300	CHASSIS No.	SG5-069261
--------	---------	-------------	------------

DATE 2021/ 4/28

1	TIMING BELT CHANGE	YES	KM	13	POWER WINDOW (R FRONT)	OK	NG			NONE			
2	COOLANT LEVEL	OK	LEAK		14	POWER WINDOW (L FRONT)	OK	NG		NONE			
3	ENGINE OIL LEVEL	OK	DIRT		15	POWER WINDOW (R REAR)	OK	NG		NONE			
4	OIL LEAKING	OK	SMALL	BIG	16	POWER WINDOW (L REAR)	OK	NG		NONE			
5	TIRE (R FRONT)	OK	225/50 R17	RFT	17	A/C CONDITION	OK	NG	WIND BLOWS OK	CAN'T OPERATE	A/C NONE		
6	TIRE (L FRONT)	OK	/	R	RFT	18	INTERIOR CONDITION	OK	NG	DIRT	SMOKING SMELL	OTHER SMELL	
7	TIRE (R REAR)	OK	/	R	RFT	19	CHECK / WARNING LAMP	OK	E/G	ABS	AIRBAG	OTHER	
8	TIRE (L REAR)	OK	/	R	RFT	(COMMENT) 9 9 27! 9 4 27! 3 10 27! カ-ハカ-マシ 26, 27 28 29. シナ. 27-27-1!					TESTER CHECK		
9	ENGINE NOISE	OK	E/G	OTHERS									
10	ENGINE CONDITION	OK	IDLING	SMOKE									
11	EXHAUST LEAK	OK	MUFFLER RUSTY	MISSING PARTS									
12	TRANSMISSION (AT / MT)	OK	SHOCK	NOISE	SLIP								
OPTION													
RADIO		C D		DVD		SUN ROOF		FLIP DOWN MONITOR					
REAR MONITOR		BACK CAMERA		CRUISE CONTROL		POWER SLIDING DOOR (LEFT)		POWER SLIDING DOOR (RIGHT)					
POWER BACK DOOR													
(注意) オプション品が付いていて作動するものは「O」、付いていて作動しないものは「×」、オプション品が付いていないものは「無印」でお願いします。 (注意) NGが入った項目は、窓ガラスに記載せずコメントにすべて記載をお願いします。オークションシートをチェックして、U3・B3以上の凹みキズ、フロントガラスの割れやヒビ(マーカで囲んで)、その他目立つ破損部分があった場合は、写真撮影をお願いします。													

YARD	ECL 富津
------	--------

INSPECTER	[Signature]
-----------	-------------

AA SHEET	9
----------	---