

## CONDITION CHECK REPORT

BK No.	317209	CHASSIS No.	HA4-222/156	DATE	2021/9/22
--------	--------	-------------	-------------	------	-----------

1	TIMING BELT CHANGE	YES	KM	13	POWER WINDOW (R FRONT)	OK	NG			(NONE)	
2	COOLANT LEVEL	OK	NG	LEAK	14	POWER WINDOW (L FRONT)	OK	NG		(NONE)	
3	ENGINE OIL LEVEL	OK	NG	DIRT	15	POWER WINDOW (R REAR)	OK	NG		NONE	
4	OIL LEAKING	OK	NG	SMALL	BIG	16	POWER WINDOW (L REAR)	OK	NG	NONE	
5	TIRE (R FRONT)	OK	NG	145 27 R2	RFT	17	A/C CONDITION	OK	NG	WIND BLOWS OK CAN'T OPERATE A/C NONE	
6	TIRE (L FRONT)	OK	NG	/	R	RFT	18	INTERIOR CONDITION	OK	NG	DIRT SMOKING SMELL OTHER SMELL
7	TIRE (R REAR)	OK	NG	/	R	RFT	19	CHECK / WARNING LAMP	OK	E/G	ABS AIRBAG OTHER
8	TIRE (L REAR)	OK	NG	/	R	RFT	(COMMENT)  MT車 - 4WD  車内 汚れ、きぼみ  シートアブル - コケカ オイル 腐食			TESTER CHECK	
9	ENGINE NOISE	OK	NG	E/G	OTHERS						
10	ENGINE CONDITION	OK	NG	IDLING	SMOKE						
11	EXHAUST LEAK	OK	NG	MUFFLER RUSTY	MISSING PARTS						
12	TRANSMISSION (AT / MT)	OK	NG	SHOCK	NOISE SLIP						
OPTION											
RADIO		CD		DVD		SUN ROOF		FLIP DOWN MONITOR			
REAR MONITOR		BACK CAMERA		CRUISE CONTROL		POWER SLIDING DOOR (LEFT)		POWER SLIDING DOOR (RIGHT)			
POWER BACK DOOR											
(注意) オプション品が付いているものは「○」、付いていないものは「×」、オプション品が付いていないものは「無印」をお願いします。 (注意) NGが入った項目は、窓ガラスに記載せずコメントにすべて記載をお願いします。オークションシートをチェックして、U3・B3以上の凹みキズ、フロントガラスの割れやヒビ(マーカで困る)、その他目立つ破損部分があった場合は、写真撮影をお願いします。											

YARD	ECL 富津	INSPECTER	イズミ	AA SHEET	0
------	--------	-----------	-----	----------	---