

CONDITION CHECK REPORT

BF No.	BG170344	CHASSIS No.	LH 172-000 1764	DATE	2019 / 3 / 23
--------	-----------------	-------------	------------------------	------	----------------------

1	TIMING BELT CHANGE	YES	NO	KM	13	POWER WINDOW (R FRONT)	OK	NG	NONE	
2	COOLANT LEVEL	OK	NG	LEAK		14	POWER WINDOW (L FRONT)	OK	NG	NONE
3	ENGINE OIL LEVEL	OK	NG	DIRT		15	POWER WINDOW (R REAR)	OK	NG	NONE
4	OIL LEAKING	OK	NG	SMALL	BIG	16	POWER WINDOW (L REAR)	OK	NG	NONE
5	TIRE (R FRONT)	OK	NG	195 80 R15	RFT	17	A/C CONDITION	OK	NG	WIND BLOWS OK CAN'T OPERATE A/G NONE
6	TIRE (L FRONT)	OK	NG	195 80 R15	RFT	18	INTERIOR CONDITION	OK	NG	DIRT SMOKING SMELL OTHER SMELL
7	TIRE (R REAR)	OK	NG	195 80 R15	RFT	19	CHECK / WARNING LAMP	OK	E/G	ABS AIRBAG OTHER
8	TIRE (L REAR)	OK	NG	195 80 R15	RFT	(COMMENT) ○ 227カ-カバ-、E/G 11M10Y 11V 10カ ○ A/C ベルト欠、A/C 交換が必要 ○ 車内全体汚い ○ シート破れ ○ シート・ドア内張 交換				
9	ENGINE NOISE	OK	NG	E/G	OTHERS					
10	ENGINE CONDITION	OK	NG	IDLING	SMOKE					
11	EXHAUST LEAK	OK	NG	MUFFLER RUSTY	MISSING PARTS					
12	TRANSMISSION (AT / MT)	OK	NG	SHOCK	NOISE SLIP					
OPTION							TESTER CHECK			
RADIO		CD		DVD		SUN ROOF		FLIP DOWN MONITOR		
REAR MONITOR		BACK CAMERA		CRUISE CONTROL		POWER SLIDING DOOR (LEFT)		POWER SLIDING DOOR (RIGHT)		
POWER BACK DOOR										
(注意) オプション品が付いていて作動するものは「○」、付いていて作動しないものは「×」、オプション品が付いていないものは「無印」でお願いします。							(注意) NGが入った項目は、窓ガラスに記載せずフロントガラスにすべて記載をお願いします。オプションシートをチェックして、U3・B3以上の凹みキズ、フロントガラスの割れやヒビ(マーカで囲んで)、その他目立つ破損部分があった場合は、写真撮影をお願いします。			

YARD	ナガセ自動車株式会社	INSPECTOR	栗岡	AA SHEET
------	-------------------	-----------	-----------	----------