

CONDITION CHECK REPORT

BG No. 174396

CHASSIS No.

WBAV676010NL69340

DATE

20¹⁹ / 3 / 29

1	TIMING BELT CHANGE	YES		KM	13 POWER WINDOW (R FRONT)	OK	NG	NONE		
2	COOLANT LEVEL	OK	NG	LEAK	14 POWER WINDOW (L FRONT)	OK	NG	NONE		
3	ENGINE OIL LEVEL	OK	NG	DIRT	15 POWER WINDOW (R REAR)	OK	NG	NONE		
4	OIL LEAKING	OK	NG	SMALL EIG	16 POWER WINDOW (L REAR)	OK	NG	NONE		
5	TIRE (R FRONT)	OK	NG	205/55R16 RFT	17 AIR CONDITION	OK	NG	WIND BLOWS OK	NONE	
6	TIRE (L FRONT)	OK	NG	/ R RFT	18 INTERIOR CONDITION	OK	NG	DIRT	SMOKING SMELL	OTHER SMELL
7	TIRE (R REAR)	OK	NG	/ R RFT	19 CHECK / WARNING LAMP	OK	E/G	ABS	AIRBAG	OTHER
8	TIRE (L REAR)	OK	NG	/ R RFT	(COMMENT) ・スポンジ付、シヤッキ無し					
9	ENGINE NOISE	OK	NG	E/G OTHERS						
10	ENGINE CONDITION	OK	NG	IDLING SMOKE						
11	EXHAUST LEAK	OK	NG	MUFFLER RUSTY MISSING PARTS						
12	TRANSMISSION (AT / MT)	OK	NG	SHOCK NOISE SLIP						
OPTION RADIO CD DVD SUN ROOF FLIP DOWN MONITOR REAR MONITOR BACK CAMERA CRUISE CONTROL POWER SLIDING DOOR (LEFT) POWER SLIDING DOOR (RIGHT) POWER BACK DOOR										
(注意) オプション品が付いていて作動するものは「O」、付いていて作動しないものは「X」、オプション品が付いていないものは「無印」でお願します。					(注意) NGが入った項目は、窓ガラスに記載せずコメントにすべて記載をお願いします。オークションシートをチェックして、U3・B3以上の凹みキズ、フロントガラスの割れやエビ(マークで蓋んで)、その他目立つ瑕疵部分があった場合は、写真撮影をお願いします。					

Yard	ECL 新門司	Inspector	KK2	AA SHEET
------	---------	-----------	-----	----------