

CONDITION CHECK REPORT

BG No.	177129	CHASSIS No.	UGF22-006136	DATE	2019 / 3 / 29
--------	--------	-------------	--------------	------	---------------

1	TIMING BELT CHANGE	YES		KM	13	POWER WINDOW (R FRONT)	OK	NG			NONE	
2	COOLANT LEVEL	OK	NG	LEAK		14	POWER WINDOW (L FRONT)	OK	NG		NONE	
3	ENGINE OIL LEVEL	OK	NG	DIRT		15	POWER WINDOW (R REAR)	OK	NG		NONE	
4	OIL LEAKING	OK	NG	SMALL	BIG	16	POWER WINDOW (L REAR)	OK	NG		NONE	
5	TIRE (R FRONT)	OK	NG	175 R14	RFT	17	AIR CONDITION	OK	NG	WIND BLOWS OK	NONE	
6	TIRE (L FRONT)	OK	NG	↓ R	RFT	18	INTERIOR CONDITION	OK	NG	DIRT	SMOKING SMELL OTHER SMELL	
7	TIRE (R REAR)	OK	NG	145 R12	RFT	19	CHECK / WARNING LAMP	OK	E/G	ABS	AIRBAG OTHER	
8	TIRE (L REAR)	OK	NG	↓ R	RFT	(COMMENT) ・A/C冷風出ない。 ・室内天張汚れ。 ・内張破れ。 ・D-N席汚れ。 ・シラ-欠品 ・シフトブーツ破損						
9	ENGINE NOISE	OK	NG	E/G	OTHERS							
10	ENGINE CONDITION	OK	NG	IDLING	SMOKE							
11	EXHAUST LEAK	OK	NG	MUFFLER RUSTY	MISSING PARTS							
12	TRANSMISSION (AT/MT)	OK	NG	SHOCK	NOISE							SLIP
OPTION												
<input checked="" type="checkbox"/>	RADIO	<input type="checkbox"/>	C D	<input type="checkbox"/>	DVD	<input type="checkbox"/>	SUN ROOF	<input type="checkbox"/>	FLIP DOWN MONITOR			
<input type="checkbox"/>	REAR MONITOR	<input type="checkbox"/>	BACK CAMERA	<input type="checkbox"/>	CRUISE CONTROL	<input type="checkbox"/>	POWER SLIDING DOOR (LEFT)	<input type="checkbox"/>	POWER SLIDING DOOR (RIGHT)			
<input type="checkbox"/>	POWER BACK DOOR											
(注意) オプション品が付いていて作動するものは「○」、付いていて作動しないものは「×」、オプション品が付いていないものは「無印」でお願いします。							(注意) NGが入った項目は、窓ガラスに記載せずコメントにすべて記載をお願いします。オークションシートをチェックして、U3・B3以上の傷みキズ、フロントガラスの割れやヒビ(マーカで囲んで)、その他目立つ破損部分があった場合は、写真撮影をお願いします。					
Yard	G		Inspector	伊藤			AA SHEET	✓				