

CONDITION CHECK REPORT

No.	BG180705	CHASSIS No.	DA52T-230915			DATE	2019 / 04 / 04		
-----	----------	-------------	--------------	--	--	------	----------------	--	--

No.	Item	Status	Sub-Item	Detail	Status	Status	Status	Status	Status	
1	TIMING BELT CHANGE	YES								
2	COOLANT LEVEL	OK	LEAK						NONE	
3	ENGINE OIL LEVEL	OK	DIRT						NONE	
4	OIL LEAKING	OK	SMALL	BIG					NONE	
5	TIRE (R FRONT)	OK	145 / 80 R 12	RFT					WIND BLOWS OK / CAN'T OPERATE / A/C NONE	
6	TIRE (L FRONT)	OK	145 / 80 R 12	RFT					DIRT / SMOKING SMELL / OTHER SMELL	
7	TIRE (R REAR)	OK	145 / 80 R 12	RFT					ABS / AIRBAG / OTHER	
8	TIRE (L REAR)	OK	145 / 80 R 12	RFT	(COMMENT) OIL LEAKING: NG : SMALL オイルしみ(ヘッドボデイ) 天張り黄ばみ。 シート破れ大(カバー取り付け)				TESTER CHECK	
9	ENGINE NOISE	OK	E/G	OTHERS						
10	ENGINE CONDITION	OK	IDLING	SMOKE						
11	EXHAUST LEAK	OK	MUFFLER RUSTY	MISSING PARTS						
12	TRANSMISSION (AT / MT)	OK	SHOCK	NOISE					SLIP	
OPTION										
<input checked="" type="checkbox"/>	RADIO									
	C D									
	DVD									
	SUN ROOF									
	FLIP DOWN MONITOR									
	REAR MONITOR		BACK CAMERA		CRUISE CONTROL		POWER SLIDING DOOR (LEFT)		POWER SLIDING DOOR (RIGHT)	
	POWER BACK DOOR									

(注意) オプション品が付いていて作動するのは「○」、付いていて作動しないものは「×」、オプション品が付いていないものは「無印」でお願いします。

(注意) NGが入った項目は、窓ガラスに記載せずコメントにすべて記載をお願いします。オークションシートをチェックして、U3・B3以上の凹みキズ、フロントガラスの割れやヒビ(マーカーで囲んで)、その他目立つ破損部分があった場合は、写真撮影をお願いします。

YARD	藤原AC第3
------	--------

INSPECTER	fudano
-----------	--------

AA SHEET	<input checked="" type="checkbox"/>
----------	-------------------------------------