

CONDITION CHECK REPORT

BF No. <u>PC7183124</u>	CHASSIS No. <u>D53A-5000203</u>
-------------------------	---------------------------------

DATE 2017 / 4 / 3

1	TIMING BELT CHANGE	YES	NG	LEAK	DIRT	SMALL	BIG	KM	13	POWER WINDOW (R FRONT)	OK	NG	NONE				
2	COOLANT LEVEL	OK	NG						14	POWER WINDOW (L FRONT)	OK	NG	NONE				
3	ENGINE OIL LEVEL	OK	NG						15	POWER WINDOW (R REAR)	OK	NG	NONE				
4	OIL LEAKING	OK	NG						16	POWER WINDOW (L REAR)	OK	NG	NONE				
5	TIRE (R FRONT)	OK	NG	205 50 R 16		RFT			17	A/C CONDITION	OK	NG	WIND BLOWS OK CAN'T OPERATE A/C NONE				
6	TIRE (L FRONT)	OK	NG	/	R	RFT			18	INTERIOR CONDITION	OK	NG	DIRT SMOKING SMELL OTHER SMELL				
7	TIRE (R REAR)	OK	NG	/	R	RFT			19	CHECK / WARNING LAMP	OK	E/G	ABS AIRBAG OTHER				
8	TIRE (L REAR)	OK	NG	/	R	RFT			(COMMENT) E/S 通りオイルエビ ホ-702 自動換 手動なら可能 (注意) NGが入った項目は、窓ガラスに記載せずコメントにすべて記載をお願いします。 オークションシートをチェックして、U3・B3以上の凹みキズ、フロントガラスの割れやヒビ(マーカーで囲んで)、その他目立つ破損部分があった場合は、写真撮影をお願いします。								
9	ENGINE NOISE	OK	NG	E/G	OTHERS								TESTER CHECK				
10	ENGINE CONDITION	OK	NG	IDLING	SMOKE												
11	EXHAUST LEAK	OK	NG	MUFFLER RUSTY	MISSING PARTS												
12	TRANSMISSION (AT / MT)	OK	NG	SHOCK	NOISE	SLIP											
OPTION																	
RADIO		CD		BVD		SUN ROOF		FLIP DOWN MONITOR									
REAR MONITOR		BACK CAMERA		CRUISE CONTROL		POWER SLIDING DOOR (LEFT)		POWER SLIDING DOOR (RIGHT)									
POWER BACK DOOR																	

YARD 富津 ECL

INSPECTER カサハラ

AA SHEET 7