

CONDITION CHECK REPORT

BF No.	BG186151	CHASSIS No.	WDD2040482A420848	DATE	2019 / 4 / 17
--------	----------	-------------	-------------------	------	---------------

1	TIMING BELT CHANGE	<input type="radio"/>	YES		KM	13	POWER WINDOW (R FRONT)	<input checked="" type="radio"/>	NG			NONE						
2	COOLANT LEVEL	<input checked="" type="radio"/>	NG	LEAK			14	POWER WINDOW (L FRONT)	<input checked="" type="radio"/>	NG		NONE						
3	ENGINE OIL LEVEL	<input checked="" type="radio"/>	NG	DIRT			15	POWER WINDOW (R REAR)	<input checked="" type="radio"/>	NG		NONE						
4	OIL LEAKING	<input checked="" type="radio"/>	NG	SMALL	BIG		16	POWER WINDOW (L REAR)	<input checked="" type="radio"/>	NG		NONE						
5	TIRE (R FRONT)	<input checked="" type="radio"/>	NG	205/55R16		RFT	17	A/C CONDITION	<input checked="" type="radio"/>	NG	WIND BLOWS OK	CAN'T OPERATE	NONE					
6	TIRE (L FRONT)	<input checked="" type="radio"/>	NG	205/55R16		RFT	18	INTERIOR CONDITION	<input checked="" type="radio"/>	NG	DIRT	SMOKING SMELL	OTHER SMELL					
7	TIRE (R REAR)	<input checked="" type="radio"/>	NG	205/55R16		RFT	19	CHECK / WARNING LAMP	<input checked="" type="radio"/>	E/G	ABS	AIRBAG	OTHER					
8	TIRE (L REAR)	<input checked="" type="radio"/>	NG	205/55R16		RFT	(COMMENT)				TESTER CHECK							
9	ENGINE NOISE	<input checked="" type="radio"/>	NG	E/G	OTHERS													
10	ENGINE CONDITION	<input checked="" type="radio"/>	NG	IDLING	SMOKE													
11	EXHAUST LEAK	<input checked="" type="radio"/>	NG	MUFFLER RUSTY	MISSING PARTS													
12	TRANSMISSION (AT / MT)	<input checked="" type="radio"/>	NG	SHOCK	NOISE	SLIP												
OPTION																		
<input checked="" type="radio"/> RADIO		<input checked="" type="radio"/> C D		<input checked="" type="radio"/> DVD														
		<input checked="" type="radio"/> BACK CAMERA		<input checked="" type="radio"/> CRUISE CONTROL														
(注意) オプション品が付いていて作動するものは「○」、付いていて作動しないものは「×」、オプション品が付いていないものは「無印」でお願いします。							(注意) NGが入った項目は、窓ガラスに記載せずコメントにすべて記載をお願いします。オークションシートをチェックして、U3・B3以上の凹みキズ、フロントガラスの割れやヒビ(マーカで囲んで)、その他目立つ破損部分があった場合は、写真撮影をお願いします。											

YARD	神戸(サンフェニックスRS-B)
------	------------------

INSPECTER	島田
-----------	----

AA SHEET	<input checked="" type="checkbox"/>
----------	-------------------------------------