

CONDITION CHECK REPORT

5276 7357-

BG No.	295673	CHASSIS No.	FK71DJ-770134
--------	--------	-------------	---------------

DATE 2019/5/9

1	TIMING BELT CHANGE	YES	KM	13	POWER WINDOW (R FRONT)	OK	NG			NONE		
2	COOLANT LEVEL	OK	LEAK		14	POWER WINDOW (L FRONT)	OK	NG		NONE		
3	ENGINE OIL LEVEL	OK	DIRT		15	POWER WINDOW (R REAR)	OK	NG		NONE		
4	OIL LEAKING	OK	SMALL	BIG	16	POWER WINDOW (L REAR)	OK	NG		NONE		
5	TIRE (R FRONT)	OK	225/80 R.75	RFT	17	A/C CONDITION	OK	NG	WIND BLOWS OK	CAN'T OPERATE	A/C NONE	
6	TIRE (L FRONT)	OK	225/80 R.75	RFT	18	INTERIOR CONDITION	OK	NG	DIRT	SMOKING SMELL	OTHER SMELL	
7	TIRE (R REAR)	OK	225/80 R.75	RFT	19	CHECK / WARNING LAMP	OK	E/G	ABS	AIRBAG	OTHER	
8	TIRE (L REAR)	OK	225/80 R.75	RFT	(COMMENT) 左右のフィルター シートカバー(本) ABSランプ点灯 ジョッキ、スノコ、T 欠品						TESTER CHECK	
9	ENGINE NOISE	OK	E/G	OTHERS								
10	ENGINE CONDITION	OK	IDLING	SMOKE								
11	EXHAUST LEAK	OK	MUFFLER RUSTY	MISSING PARTS								
12	TRANSMISSION (AT / MT)	OK	SHOCK	NOISE							SLIP	
OPTION												
RADIO		C D		DVD		SUN ROOF		FLIP DOWN MONITOR				
REAR MONITOR		BACK CAMERA		CRUISE CONTROL		POWER SLIDING DOOR (LEFT)		POWER SLIDING DOOR (RIGHT)				
POWER BACK DOOR												
(注意) オプション品が付いていて作動するものは「O」、付いていて作動しないものは「x」、オプション品が付いていないものは「無印」をお願いします。						(注意) NGが入った項目は、窓ガラスに記載せずコメントにすべて記載をお願いします。オークションシートをチェックして、U3-B3以上の凹みキズ、フロントガラスの割れやヒビ(マーカで囲んで)、その他目立つ破損部分があった場合は、写真撮影をお願いします。						

YARD	マツミ
------	-----

INSPECTER	指 野
-----------	-----

AA SHEET	L
----------	---