

# CONDITION CHECK REPORT

BG No.	312 897	CHASSIS No.	NPR 32C1-3002952
--------	---------	-------------	------------------

DATE 2019/5/13

1	TIMING BELT CHANGE		YES		KM	13	POWER WINDOW (R FRONT)	(OK)	NG				NONE	
2	COOLANT LEVEL	(OK)	NG	LEAK		14	POWER WINDOW (L FRONT)	(OK)	NG				NONE	
3	ENGINE OIL LEVEL	(OK)	NG	DIRT		15	POWER WINDOW (R REAR)	OK	NG				(NONE)	
4	OIL LEAKING	(OK)	NG	SMALL	BIG	16	POWER WINDOW (L REAR)	OK	NG				(NONE)	
5	TIRE (R FRONT)	(OK)	NG	7.50'	R/B	RFT	17	A/C CONDITION	OK	NG	WIND BLOWS OK	CAN'T OPERATE	(A/C NONE)	
6	TIRE (L FRONT)	(OK)	NG	/	R	RFT	18	INTERIOR CONDITION	OK	(NG)	DIRT	SMOKING SMELL	OTHER SMELL	
7	TIRE (R REAR)	(OK)	NG	/	R x2	RFT	19	CHECK / WARNING LAMP	(OK)	E/G	ABS	AIRBAG	OTHER	
8	TIRE (L REAR)	(OK)	NG	/	R	RFT	(COMMENT)  A/C BENT 切りかかし          (注意) NGが入った項目は、窓ガラスに記載せずコメントにすべて記載をお願いします。 オークションシートをチェックして、U3・B3以上の凹みキズ、フロントガラスの割れやヒビ(マーカ で囲んで)、その他目立つ破損部分があった場合は、写真撮影をお願いします。						TESTER CHECK	
9	ENGINE NOISE	(OK)	NG	E/G	OTHERS									
10	ENGINE CONDITION	OK	(NG)	IDLING	(SMOKE)									
11	EXHAUST LEAK	(OK)	NG	MUFFLER RUSTY	MISSING PARTS									
12	TRANSMISSION (AT / MT)	(OK)	NG	SHOCK	NOISE	SLIP								
OPTION														
(RADIO)	C D	DVD	SUN ROOF	FLIP DOWN MONITOR										
REAR MONITOR	BACK CAMERA	CRUISE CONTROL	POWER SLIDING DOOR (LEFT)	POWER SLIDING DOOR (RIGHT)										
POWER BACK DOOR														

YARD	ECL新門司	INSPECTER	m + 林	AA SHEET	✓
------	--------	-----------	-------	----------	---