

Legacy B4

CONDITION CHECK REPORT

BG No. 313617 CHASSIS No. BL5-003326

DATE 2019 / 5 / 18

| | | | | | | | | | | | | | |
|-----------------|------------------------|----------------|---------------------------|----------------------------|---------------|-------------------------|------------------------|----|-----|---------------|---------------|--------------|--|
| 1 | TIMING BELT CHANGE | NO | YES | | KM | 13 | POWER WINDOW (R FRONT) | OK | NG | | | NONE | |
| 2 | COOLANT LEVEL | OK | NG | LEAK | | 14 | POWER WINDOW (L FRONT) | OK | NG | | | NONE | |
| 3 | ENGINE OIL LEVEL | OK | NG | DIRT | | 15 | POWER WINDOW (R REAR) | OK | NG | | | NONE | |
| 4 | OIL LEAKING | OK | NG | SMALL | BIG | 16 | POWER WINDOW (L REAR) | OK | NG | | | NONE | |
| 5 | TIRE (R FRONT) | OK | NG | 225 45 R18 | RFT | 17 | A/C CONDITION | OK | NG | WIND BLOWS OK | CAN'T OPERATE | A/C NONE | |
| 6 | TIRE (L FRONT) | OK | NG | 225 45 R18 | RFT | 18 | INTERIOR CONDITION | OK | NG | DIRT | SMOKING SMELL | OTHER SMELL | |
| 7 | TIRE (R REAR) | OK | NG | 225 45 R18 | RFT | 19 | CHECK / WARNING LAMP | OK | E/G | ABS | AIRBAG | OTHER | |
| 8 | TIRE (L REAR) | OK | NG | 225 45 R18 | RFT | (COMMENT) CD及び不良 | | | | | | TESTER CHECK | |
| 9 | ENGINE NOISE | OK | NG | E/G | OTHERS | | | | | | | | |
| 10 | ENGINE CONDITION | OK | NG | IDLING | SMOKE | | | | | | | | |
| 11 | EXHAUST LEAK | OK | NG | MUFFLER RUSTY | MISSING PARTS | | | | | | | | |
| 12 | TRANSMISSION (AT / MT) | OK | NG | SHOCK | NOISE | | | | | | | SLIP | |
| OPTION | | | | | | | | | | | | | |
| RADIO | CD | DVD | SUN ROOF | FLIP DOWN MONITOR | | | | | | | | | |
| REAR MONITOR | BACK CAMERA | CRUISE CONTROL | POWER SLIDING DOOR (LEFT) | POWER SLIDING DOOR (RIGHT) | | | | | | | | | |
| POWER BACK DOOR | | | | | | | | | | | | | |

(注意) オプション品が付いていて作動するものは「○」、付いていて作動しないものは「×」、オプション品が付いていないものは「無印」でお願いします。

(注意) NGが入った項目は、窓ガラスに記載せずコメントにすべて記載をお願いします。オークションシートをチェックして、U3・B3以上の凹みキズ、フロントガラスの割れやヒビ(マーカーで囲んで)、その他目立つ破損部分があった場合は、写真撮影をお願いします。

YARD 野田

INSPECTER KS

AA SHEET ○