

Rush

CONDITION CHECK REPORT

BF No.	335438	CHASSIS No.	J200E-0032676
--------	--------	-------------	---------------

DATE 2019 / 6 / 8

1	TIMING BELT CHANGE	No	YES		KM	13	POWER WINDOW (R FRONT)	OK	NG			NONE	
2	COOLANT LEVEL	OK	NG	LEAK		14	POWER WINDOW (L FRONT)	OK	NG			NONE	
3	ENGINE OIL LEVEL	OK	NG	DIRT		15	POWER WINDOW (R REAR)	OK	NG			NONE	
4	OIL LEAKING	OK	NG	SMALL	BIG	16	POWER WINDOW (L REAR)	OK	NG			NONE	
5	TIRE (R FRONT)	OK	NG	215/65R16	RFT	17	A/C CONDITION	OK	NG	WIND BLOWS OK	CAN'T OPERATE	A/C NONE	
6	TIRE (L FRONT)	OK	NG	215/65R16	RFT	18	INTERIOR CONDITION	OK	NG	DIRT	SMOKING SMELL	OTHER SMELL	
7	TIRE (R REAR)	OK	NG	215/65R16	RFT	19	CHECK / WARNING LAMP	OK	E/G	ABS	AIRBAG	OTHER	
8	TIRE (L REAR)	OK	NG	215/65R16	RFT	(COMMENT) シートカバーは一部外し						TESTER CHECK	
9	ENGINE NOISE	OK	NG	E/G	OTHERS								
10	ENGINE CONDITION	OK	NG	IDLING	SMOKE								
11	EXHAUST LEAK	OK	NG	MUFFLER RUSTY	MISSING PARTS								
12	TRANSMISSION (AT/MT)	OK	NG	SHOCK	NOISE							SLIP	
OPTION													
RADIO	CD	DVD	SUN ROOF	FLIP DOWN MONITOR									
REAR MONITOR	BACK CAMERA	CRUISE CONTROL	POWER SLIDING DOOR (LEFT)	POWER SLIDING DOOR (RIGHT)									
POWER BACK DOOR													
(注意) オプション品が付いていて作動するのは「○」、付いていて作動しないものは「×」、オプション品が付いていないものは「無印」でお願いします。						(注意) NGが入った項目は、窓ガラスに記載せずコメントにすべて記載をお願いします。オークションシートをチェックして、U3・B3以上の凹みキズ、フロントガラスの割れやヒビ(マーカで囲んで)、その他目立つ破損部分があった場合は、写真撮影をお願いします。							

YARD	DF
------	----

INSPECTER	CS
-----------	----

AA SHEET	0
----------	---