

# CONDITION CHECK REPORT

|        |          |             |              |      |               |
|--------|----------|-------------|--------------|------|---------------|
| BF No. | BG336680 | CHASSIS No. | VPE25-005158 | DATE | 2019 / 6 / 11 |
|--------|----------|-------------|--------------|------|---------------|

|        |                          |    |     |               |               |      |  |    |     |               |               |             |
|--------|--------------------------|----|-----|---------------|---------------|------|--|----|-----|---------------|---------------|-------------|
| 1      | TIMING BELT CHANGE       |    | YES |               | KM            | 13   | POWER WINDOW (R FRONT)   | OK | NG  |               |               | NONE        |
| 2      | COOLANT LEVEL            | OK | NG  | LEAK          |               |      | 14 POWER WINDOW (L FRONT)  | OK | NG  |               |               | NONE        |
| 3      | ENGINE OIL LEVEL         | OK | NG  | DIRT          |               |      | 15 POWER WINDOW (R REAR)   | OK | NG  |               |               | NONE        |
| 4      | OIL LEAKING              | OK | NG  | SMALL         | BIG           |      | 16 POWER WINDOW (L REAR)   | OK | NG  |               |               | NONE        |
| 5      | TIRE (R FRONT)           | OK | NG  | 195/80R15     |               | RFT  | 17 A/C CONDITION   | OK | NG  | WIND BLOWS OK | CAN'T OPERATE | NONE        |
| 6      | TIRE (L FRONT)           | OK | NG  | 195/80R15     |               | RFT  | 18 INTERIOR CONDITION  | OK | NG  | DIRT          | SMOKING SMELL | OTHER SMELL |
| 7      | TIRE (R REAR)            | OK | NG  | 185/70R14     |               | RFT  | 19 CHECK / WARNING LAMP  | OK | E/G | ABS           | AIRBAG        | OTHER       |
| 8      | TIRE (L REAR)            | OK | NG  | 185/70R14     |               | RFT  | (COMMENT)  |    |     |               | TESTER CHECK  |             |
| 9      | ENGINE NOISE             | OK | NG  | E/G           | OTHERS        |      |  |    |     |               |               |             |
| 10     | ENGINE CONDITION         | OK | NG  | IDLING        | SMOKE         |      |  |    |     |               |               |             |
| 11     | EXHAUST LEAK             | OK | NG  | MUFFLER RUSTY | MISSING PARTS |      |  |    |     |               |               |             |
| 12     | TRANSMISSION ( AT / MT ) | OK | NG  | SHOCK         | NOISE         | SLIP |  |    |     |               |               |             |
| OPTION |                          |    |     |               |               |      |  |    |     |               |               |             |
|        |                          |    |     |               |               |      | (注意) NGが入った項目は、窓ガラスに記載せずコメントにすべて記載をお願いします。<br>オークションシートをチェックして、U3・B3以上の凹みキズ、フロントガラスの割れやヒビ(マーカ-で囲んで)、その他目立つ破損部分があった場合は、写真撮影をお願いします。 |    |     |               |               |             |

|      |             |
|------|-------------|
| YARD | 木更津・畑沢(SPX) |
|------|-------------|

|           |     |
|-----------|-----|
| INSPECTER | 佐久間 |
|-----------|-----|

|          |   |
|----------|---|
| AA SHEET | ✓ |
|----------|---|