

CONDITION CHECK REPORT

BF No. 89372175	CHASSIS No. GP2-027680
------------------------	-------------------------------

DATE **2019 / 7 / 11**

No.	Item	OK	NG	Leak / Dirt / Small / Big	Tire / Wheel	Kilometers	Item	OK	NG	E/G	Other
1	TIMING BELT CHANGE		YES				13 POWER WINDOW (R FRONT)	OK	NG		NONE
2	COOLANT LEVEL	OK	NG	LEAK			14 POWER WINDOW (L FRONT)	OK	NG		NONE
3	ENGINE OIL LEVEL	OK	NG	DIRT			15 POWER WINDOW (R REAR)	OK	NG		NONE
4	OIL LEAKING	OK	NG	SMALL	BIG		16 POWER WINDOW (L REAR)	OK	NG		NONE
5	TIRE (R FRONT)	OK	NG	195/65 R15		RFT	17 A/C CONDITION	OK	NG		WIND BLOWS OK / CAN'T OPERATE / A/C NONE
6	TIRE (L FRONT)	OK	NG	/	R	RFT	18 INTERIOR CONDITION	OK	NG		DIRT / SMOKING SMELL / OTHER SMELL
7	TIRE (R REAR)	OK	NG	/	R	RFT	19 CHECK / WARNING LAMP	OK	E/G		ABS / AIRBAG / OTHER
8	TIRE (L REAR)	OK	NG	/	R	RFT	(COMMENT) <div style="font-size: 2em; font-weight: bold; text-align: center;">OK - 27!</div>		TESTER CHECK		
9	ENGINE NOISE	OK	NG	E/G	OTHERS						
10	ENGINE CONDITION	OK	NG	IDLING	SMOKE						
11	EXHAUST LEAK	OK	NG	MUFFLER RUSTY	MISSING PARTS						
12	TRANSMISSION (AT / MT)	OK	NG	SHOCK	NOISE	SLIP					
OPTION											
<input checked="" type="checkbox"/> RADIO	<input checked="" type="checkbox"/> CD	<input checked="" type="checkbox"/> DVD	<input type="checkbox"/> SUN ROOF		<input type="checkbox"/> FLIP DOWN MONITOR						
<input type="checkbox"/> REAR MONITOR	<input type="checkbox"/> BACK CAMERA	<input type="checkbox"/> CRUISE CONTROL	<input type="checkbox"/> POWER SLIDING DOOR (LEFT)		<input type="checkbox"/> POWER SLIDING DOOR (RIGHT)						
<input type="checkbox"/> POWER BACK DOOR											
(注意) オプション品が付いていて作動するものは「○」、付いていて作動しないものは「×」、オプション品が付いていないものは「無印」でお願いします。							(注意) NGが入った項目は、窓ガラスに記載せずコメントにすべて記載をお願いします。オークションシートをチェックして、U3・B3以上の凹みキズ、フロントガラスの割れやヒビ(マーカーで囲んで)、その他目立つ破損部分があった場合は、写真撮影をお願いします。				

YARD **富津 ECL**

INSPECTER **工井**

AA SHEET **0**