

CONDITION CHECK REPORT

| | |
|----------------------|----------------------------------|
| B# No. <u>45A6A0</u> | CHASSIS No. <u>NCP50-0151525</u> |
|----------------------|----------------------------------|

DATE 2019/10/15

| | | | | | | | | | | | | |
|-----------------|------------------------|----------------|---------------------------|-----------------------------|------------------------|------------------------|----|-----|---------------|---------------|-------------|--|
| 1 | TIMING BELT CHANGE | YES | KM | 13 | POWER WINDOW (R FRONT) | OK | NG | | | NONE | | |
| 2 | COOLANT LEVEL | OK | NG | LEAK | 14 | POWER WINDOW (L FRONT) | OK | NG | | NONE | | |
| 3 | ENGINE OIL LEVEL | OK | NG | DIRT | 15 | POWER WINDOW (R REAR) | OK | NG | | NONE | | |
| 4 | OIL LEAKING | OK | NG | SMALL BIG | 16 | POWER WINDOW (L REAR) | OK | NG | | NONE | | |
| 5 | TIRE (R FRONT) | OK | NG | 165' R 13 RFT | 17 | A/C CONDITION | OK | NG | WIND BLOWS OK | CAN'T OPERATE | A/C NONE | |
| 6 | TIRE (L FRONT) | OK | NG | 165' R 13 RFT | 18 | INTERIOR CONDITION | OK | NG | DIRT | SMOKING SMELL | OTHER SMELL | |
| 7 | TIRE (R REAR) | OK | NG | 165' R 13 RFT | 19 | CHECK / WARNING LAMP | OK | E/G | ABS | AIRBAG | OTHER | |
| 8 | TIRE (L REAR) | OK | NG | 165' R 13 RFT | (COMMENT) | | | | | TESTER CHECK | | |
| 9 | ENGINE NOISE | OK | NG | E/G OTHERS | | | | | | | | |
| 10 | ENGINE CONDITION | OK | NG | IDLING SMOKE | | | | | | | | |
| 11 | EXHAUST LEAK | OK | NG | MUFFLER RUSTY MISSING PARTS | | | | | | | | |
| 12 | TRANSMISSION (AT / MT) | OK | NG | SHOCK NOISE SLIP | | | | | | | | |
| OPTION | | | | | | | | | | | | |
| RADIO | C D | DVD | SUN ROOF | FLIP DOWN MONITOR | | | | | | | | |
| REAR MONITOR | BACK CAMERA | CRUISE CONTROL | POWER SLIDING DOOR (LEFT) | POWER SLIDING DOOR (RIGHT) | | | | | | | | |
| POWER BACK DOOR | | | | | | | | | | | | |

(注意) オプション品が付いていて作動するものは「○」、付いていて作動しないものは「×」、オプション品が付いていないものは「無印」でお願いします。

(注意) NGが入った項目は、窓ガラスに記載せずコメントにすべて記載をお願いします。オークションシートをチェックして、U3・B3以上の凹みキズ、フロントガラスの割れやヒビ(マーカで囲んで)、その他自立つ破損部分があった場合は、写真撮影をお願いします。

| | |
|------|-------------------|
| YARD | <u>カナロア 丹勢湾海運</u> |
|------|-------------------|

| | |
|-----------|--------------|
| INSPECTER | <u>177 =</u> |
|-----------|--------------|

| | |
|----------|-------------------------------------|
| AA SHEET | <input checked="" type="checkbox"/> |
|----------|-------------------------------------|