

CONDITION CHECK REPORT

BF No. BG 473717	CHASSIS No. CREW-106277	DATE 2019 / 8 / 21
-------------------------	--------------------------------	---------------------------

1	TIMING BELT CHANGE	YES	KM	13	POWER WINDOW (R FRONT)	(OK)	NG	NONE			
2	COOLANT LEVEL	(OK) NG	LEAK	14	POWER WINDOW (L FRONT)	(OK)	NG	NONE			
3	ENGINE OIL LEVEL	(OK) NG	DIRT	15	POWER WINDOW (R REAR)	(OK)	NG	NONE			
4	OIL LEAKING	(OK) NG	SMALL BIG	16	POWER WINDOW (L REAR)	(OK)	NG	NONE			
5	TIRE (R FRONT)	(OK) NG	19565 R15 RFT	17	A/C CONDITION	(OK)	NG	WIND BLOWS OK	CAN'T OPERATE	A/C NONE	
6	TIRE (L FRONT)	(OK) NG	19565 R15 RFT	18	INTERIOR CONDITION	(OK)	NG	DIRT	SMOKING SMELL	OTHER SMELL	
7	TIRE (R REAR)	(OK) NG	19565 R15 RFT	19	CHECK / WARNING LAMP	(OK)	E/G	ABS	AIRBAG	OTHER	
8	TIRE (L REAR)	(OK) NG	19565 R15 RFT	(COMMENT)				TESTER CHECK			
9	ENGINE NOISE	(OK) NG	E/G OTHERS								
10	ENGINE CONDITION	(OK) NG	IDLING SMOKE								
11	EXHAUST LEAK	(OK) NG	MUFFLER RUSTY MISSING PARTS								
12	TRANSMISSION (AT / MT)	(OK) NG	SHOCK NOISE SLIP								
OPTION											
(OK) RADIO REAR MONITOR POWER BACK DOOR	(OK) CD BACK CAMERA	DVD CRUISE CONTROL	SUN ROOF POWER SLIDING DOOR (LEFT)								
(注意) オプション品が付いていて作動するのは「O」、付いていて作動しないものは「×」、オプション品が付いていないものは「無印」でお願いします。				(注意) NGが入った項目は、窓ガラスに記載せずコメントにすべて記載をお願いします。 オークションシートをチェックして、U3・B3以上の凹みキズ、フロントガラスの割れやヒビ(マーカで囲んで)、その他目立つ破損部分があった場合は、写真撮影をお願いします。							

YARD	KANDA	INSPECTER	柳 詰	AA SHEET
------	-------	-----------	-----	----------