

CONDITION CHECK REPORT

BG No. BG475393	CHASSIS No. A8T240-0012091	DATE 2019 / 8 / 24
------------------------	-----------------------------------	---------------------------

1	TIMING BELT CHANGE	YES	KM	13	POWER WINDOW (R FRONT)	OK	NG			NONE	
2	COOLANT LEVEL	OK	LEAK		14	POWER WINDOW (L FRONT)	OK	NG		NONE	
3	ENGINE OIL LEVEL	OK	DIRT		15	POWER WINDOW (R REAR)	OK	NG		NONE	
4	OIL LEAKING	OK	SMALL	BIG	16	POWER WINDOW (L REAR)	OK	NG		NONE	
5	TIRE (R FRONT)	OK	195/65 R15		RFT	17	A/C CONDITION	OK	NG	WIND BLOWS OK CAN'T OPERATE A/C NONE	
6	TIRE (L FRONT)	OK	/	R	RFT	18	INTERIOR CONDITION	OK	NG	DIRT SMOKING SMELL OTHER SMELL	
7	TIRE (R REAR)	OK	/	R	RFT	19	CHECK / WARNING LAMP	OK	E/G	ABS AIRBAG OTHER	
8	TIRE (L REAR)	OK	/	R	RFT	(COMMENT) <div style="text-align: center; font-size: 1.2em;"> (16) 車席からは見えません (8) ミート汚水 </div>				TESTER CHECK	
9	ENGINE NOISE	OK	E/G	OTHERS							
10	ENGINE CONDITION	OK	IDLING	SMOKE							
11	EXHAUST LEAK	OK	MUFFLER RUSTY	MISSING PARTS							
12	TRANSMISSION (AT/ MT)	OK	SHOCK	NOISE	SLIP						
OPTION											
RADIO	CD	DVD	SUN ROOF	FLIP DOWN MONITOR							
REAR MONITOR	BACK CAMERA	CRUISE CONTROL	POWER SLIDING DOOR (LEFT)	POWER SLIDING DOOR (RIGHT)							
POWER BACK DOOR											
(注意) オプション品が付いていて作動するものは「○」、付いていて作動しないものは「×」、オプション品が付いていないものは「無印」でお願いします。 (注意) NGが入った項目は、窓ガラスに記載せずコメントにすべて記載をお願いします。オークションシートをチェックして、U3-B3以上の凹みキズ、フロントガラスの割れやヒビ(マーカで囲んで)、その他目立つ破損部分があった場合は、写真撮影をお願いします。											

YARD	ECL木更津	INSPECTER	泉	AA SHEET	0
------	--------	-----------	---	----------	---