

# CONDITION CHECK REPORT

B# No.	47534	CHASSIS No.	AZT240-0022434	DATE	2019 / 8 / 22
--------	-------	-------------	----------------	------	---------------

1	TIMING BELT CHANGE	YES	KM	13	POWER WINDOW (R FRONT)	OK	NG	NONE					
2	COOLANT LEVEL	OK	NG	LEAK	14	POWER WINDOW (L FRONT)	OK	NG	NONE				
3	ENGINE OIL LEVEL	OK	NG	DIRT	15	POWER WINDOW (R REAR)	OK	NG	NONE				
4	OIL LEAKING	OK	NG	SMALL BIG	16	POWER WINDOW (L REAR)	OK	NG	NONE				
5	TIRE (R FRONT)	OK	NG	195-65 R 15 RFT	17	A/C CONDITION	OK	NG	WIND BLOWS OK	CAN'T OPERATE	A/C NONE		
6	TIRE (L FRONT)	OK	NG	195-65 R 15 RFT	18	INTERIOR CONDITION	OK	NG	DIRT	SMOKING SMELL	OTHER SMELL		
7	TIRE (R REAR)	OK	NG	195-65 R 15 RFT	19	CHECK / WARNING LAMP	OK	E/G	ABS	AIRBAG	OTHER		
8	TIRE (L REAR)	OK	NG	195-65 R 15 RFT	(COMMENT)						TESTER CHECK		
9	ENGINE NOISE	OK	NG	E/G OTHERS									
10	ENGINE CONDITION	OK	NG	IDLING SMOKE									
11	EXHAUST LEAK	OK	NG	MUFFLER RUSTY MISSING PARTS									
12	TRANSMISSION (AT/MT)	OK	NG	SHOCK NOISE SLIP									
OPTION													
RADIO		C D		DVD		SUN ROOF		FLIP DOWN MONITOR					
REAR MONITOR		BACK CAMERA		CRUISE CONTROL		POWER SLIDING DOOR (LEFT)		POWER SLIDING DOOR (RIGHT)					
POWER BACK DOOR													
<p>(注意) オプション品が付いていて作動するものは「○」、付いていて作動しないものは「×」、オプション品が付いていないものは「無印」でお願いします。</p> <p>(注意) NGが入った項目は、窓ガラスに記載せずコメントにすべて記載をお願いします。オークションシートをチェックして、U3・B3以上の固みキズ、フロントガラスの割れやヒビ(マーカで囲んで)、その他自立つ破損部分があった場合は、写真撮影をお願いします。</p>													

YARD	カトー 岸勢湾海運
------	-----------

INSPECTER	新左
-----------	----

AA SHEET	✓
----------	---