

CONDITION CHECK REPORT

BG No.	X75208	CHASSIS No.	NHP10-6319573	DATE	2019 / 8 / 9
--------	--------	-------------	---------------	------	--------------

1	TIMING BELT CHANGE		YES		KM	13	POWER WINDOW (R FRONT)	OK	NG				NONE
2	COOLANT LEVEL	OK	NG	LEAK			14 POWER WINDOW (L FRONT)	OK	NG				NONE
3	ENGINE OIL LEVEL	OK	NG	DIRT			15 POWER WINDOW (R REAR)	OK	NG				NONO
4	OIL LEAKING	OK	NG	SMALL	BIG		16 POWER WINDOW (L REAR)	OK	NG				NONO
5	TIRE (R FRONT)	OK	NG	165/70 R 14		RFT	17 A/C CONDITION	OK	NG		WIND BLOWS OK	CAN'T OPERATE	A/C NONE
6	TIRE (L FRONT)	OK	NG	/		R	18 INTERIOR CONDITION	OK	NG		DIRT	SMOKING SMELL	OTHER SMELL
7	TIRE (R REAR)	OK	NG	/		R	19 CHECK / WARNING LAMP	OK	E/G		ABS	AIRBAG	OTHER
8	TIRE (L REAR)	OK	NG	/		R	(COMMENT) 18. 室内汚れ 左電格シテ不良 HV車 キーレス					TESTER CHECK	
9	ENGINE NOISE	OK	NG	E/G	OTHERS								
10	ENGINE CONDITION	OK	NG	IDLING	SMOKE								
11	EXHAUST LEAK	OK	NG	MUFFLER RUSTY	MISSING PARTS								
12	TRANSMISSION (AT MT)	OK	NG	SHOCK	NOISE	SLIP							
OPTION													
RADIO	CD			DVD		SUN ROOF		FLIP DOWN MONITOR					
REAR MONITOR	BACK CAMERA	CRUISE CONTROL		POWER SLIDING DOOR (LEFT)		POWER SLIDING DOOR (RIGHT)							
POWER BACK DOOR													
(注意) オプション品が付いていて作動するものは「O」、付いていて作動しないものは「×」、オプション品が付いていないものは「無印」でお願いします。													
(注意) NGが入った項目は、窓ガラスに記載せずコメントにすべて記載をお願いします。オークションシートをチェックして、U3-B3以上の凹みキズ、フロントガラスの割れやヒビ(マーカで囲んで)、その他目立つ破損部分があった場合は、写真撮影をお願いします。													

YARD	ECL木更津	INSPECTER	エチキ	AA SHEET	0
------	--------	-----------	-----	----------	---