

# CONDITION CHECK REPORT

Bq No. <u>475309</u>	CHASSIS No. <u>SCP92-1002485</u>	DATE <u>2019/18/20</u>
----------------------	----------------------------------	------------------------

1	TIMING BELT CHANGE	YES	KM	13	POWER WINDOW (R FRONT)	OK	NG			NONE		
2	COOLANT LEVEL	OK	NG	LEAK	14	POWER WINDOW (L FRONT)	OK	NG		NONE		
3	ENGINE OIL LEVEL	OK	NG	DIRT	15	POWER WINDOW (R REAR)	OK	NG		NONE		
4	OIL LEAKING	OK	NG	SMALL BIG	16	POWER WINDOW (L REAR)	OK	NG		NONE		
5	TIRE (R FRONT)	OK	NG	185/60 R 15 RFT	17	A/C CONDITION	OK	NG	WIND BLOWS OK	CAN'T OPERATE	A/C NONE	
6	TIRE (L FRONT)	OK	NG	185/60 R 15 RFT	18	INTERIOR CONDITION	OK	NG	DIRT	SMOKING SMELL	OTHER SMELL	
7	TIRE (R REAR)	OK	NG	185/60 R 15 RFT	19	CHECK / WARNING LAMP	OK	E/G	ABS	AIRBAG	OTHER	
8	TIRE (L REAR)	OK	NG	185/60 R 15 RFT	(COMMENT)					TESTER CHECK		
9	ENGINE NOISE	OK	NG	E/G OTHERS								
10	ENGINE CONDITION	OK	NG	IDLING SMOKE								
11	EXHAUST LEAK	OK	NG	MUFFLER RUSTY MISSING PARTS								
12	TRANSMISSION (AT / MT)	OK	NG	SHOCK NOISE SLIP								
OPTION												
RADIO	CD	DVD	SUN ROOF	FLIP DOWN MONITOR								
REAR MONITOR	BACK CAMERA	CRUISE CONTROL	POWER SLIDING DOOR (LEFT)	POWER SLIDING DOOR (RIGHT)								
POWER BACK DOOR												
(注意) オプション品が付いていて作動するものは「O」、付いていて作動しないものは「X」、オプション品が付いていないものは「無印」でお願いします。					(注意) NGが入った項目は、窓ガラスに記載せずコメントにすべて記載をお願いします。オークションシートをチェックして、U3・B3以上の割みキズ、フロントガラスの割れやヒビ(マーカで囲んで)、その他自立つ破損部分があった場合は、写真撮影をお願いします。							

YARD	<u>カトー 丹勢湾海運</u>
------	------------------

INSPECTER	<u>シウ</u>
-----------	-----------

AA SHEET	✓
----------	---