

CONDITION CHECK REPORT

BG No. B9477041	CHASSIS No. BP5-129781	DATE 2019 / 8 / 20
------------------------	-------------------------------	--------------------

1	TIMING BELT CHANGE		YES		KM	13	POWER WINDOW (R FRONT)	OK	NG			NONE	
2	COOLANT LEVEL	OK	NG	LEAK		14	POWER WINDOW (L FRONT)	OK	NG			NONE	
3	ENGINE OIL LEVEL	OK	NG	DIRT		15	POWER WINDOW (R REAR)	OK	NG			NONE	
4	OIL LEAKING	OK	NG	SMALL	BIG	16	POWER WINDOW (L REAR)	OK	NG			NONE	
5	TIRE (R FRONT)	OK	NG	215/45R17		RFT	17	A/C CONDITION	OK	NG	WIND BLOWS OK	CAN'T OPERATE	A/C NONE
6	TIRE (L FRONT)	OK	NG	/	R	RFT	18	INTERIOR CONDITION	OK	NG	DIRT	SMOKING SMELL	OTHER SMELL
7	TIRE (R REAR)	OK	NG	/	R	RFT	19	CHECK / WARNING LAMP	OK	E/G	ABS	AIRBAG	OTHER
8	TIRE (L REAR)	OK	NG	/	R	RFT	(COMMENT) ↓ 18. 室内汚れ 4WD キーレス					TESTER CHECK	
9	ENGINE NOISE	OK	NG	E/G	OTHERS								
10	ENGINE CONDITION	OK	NG	IDLING	SMOKE								
11	EXHAUST LEAK	OK	NG	MUFFLER RUSTY	MISSING PARTS								
12	TRANSMISSION (AT MT)	OK	NG	SHOCK	NOISE	SLIP							
OPTION													
RADIO		CD		DVD		SUN ROOF		FLIP DOWN MONITOR					
REAR MONITOR		BACK CAMERA		CRUISE CONTROL		POWER SLIDING DOOR (LEFT)		POWER SLIDING DOOR (RIGHT)					
POWER BACK DOOR													
(注意) オプション品が付いていて作動するものは「O」、付いていて作動しないものは「×」、オプション品が付いていないものは「無印」でお願いします。													
(注意) NGが入った項目は、窓ガラスに記載せずコメントにすべて記載をお願いします。オークションシートをチェックして、U3・B3以上の凹みキズ、フロントガラスの割れやヒビ(マーカーで囲んで)、その他目立つ破損部分があった場合は、写真撮影をお願いします。													

YARD	ECL木更津	INSPECTER	マサキ	AA SHEET	0
------	--------	-----------	-----	----------	---