

# CONDITION CHECK REPORT

BG No. <b>87485891</b>	CHASSIS No. <b>ANM10-0001427</b>	DATE 2019 / 8 / 22
------------------------	----------------------------------	--------------------

1	TIMING BELT CHANGE		YES		KM	13	POWER WINDOW (R FRONT)	(OK)	NG			NONE		
2	COOLANT LEVEL	(OK)	NG	LEAK			14	POWER WINDOW (L FRONT)	(OK)	NG		NONE		
3	ENGINE OIL LEVEL	(OK)	NG	DIRT			15	POWER WINDOW (R REAR)	(OK)	NG		NONE		
4	OIL LEAKING	(OK)	NG	SMALL	BIG		16	POWER WINDOW (L REAR)	(OK)	NG		NONE		
5	TIRE (R FRONT)	(OK)	NG	195/65 R15	RFT		17	A/C CONDITION	(OK)	NG	WIND BLOWS OK	CAN'T OPERATE	A/C NONE	
6	TIRE (L FRONT)	(OK)	NG	/ / R	RFT		18	INTERIOR CONDITION	OK	(NG)	(DIRT)	SMOKING SMELL	OTHER SMELL	
7	TIRE (R REAR)	(OK)	NG	/ / R	RFT		19	CHECK / WARNING LAMP	(OK)	E/G	ABS	AIRBAG	OTHER	
8	TIRE (L REAR)	(OK)	NG	/ / R	RFT		(COMMENT) 18. 室内汚れ ガンバイザー下  フロントガラス付 スマートキー  (注意) NGが入った項目は、窓ガラスに記載せずコメントにすべて記載をお願いします。 オークションシートをチェックして、U3・B3以上の凹みキズ、フロントガラスの割れやヒビ(マーカ で囲んで)、その他目立つ破損部分があった場合は、写真撮影をお願いします。					TESTER CHECK		
9	ENGINE NOISE	(OK)	NG	E/G	OTHERS									
10	ENGINE CONDITION	(OK)	NG	IDLING	SMOKE									
11	EXHAUST LEAK	(OK)	NG	MUFFLER RUSTY	MISSING PARTS									
12	TRANSMISSION (AT/ MT)	(OK)	NG	SHOCK	NOISE	SLIP								
OPTION														
(RADIO)		(CD)		DVD		SUN ROOF		FLIP DOWN MONITOR						
REAR MONITOR		BACK CAMERA		CRUISE CONTROL		POWER SLIDING DOOR (LEFT)		POWER SLIDING DOOR (RIGHT)						
POWER BACK DOOR														

YARD	ECL木更津	INSPECTER	2-アキ	AA SHEET	9
------	--------	-----------	------	----------	---