

# CONDITION CHECK REPORT

BF No.	BG507987	CHASSIS No.	KA51-7124686
--------	----------	-------------	--------------

DATE 2019 / 9 / 10

1	TIMING BELT CHANGE	OK	NG	YES	KM	13	POWER WINDOW (R FRONT)	OK	NG	NONE
2	COOLANT LEVEL	OK	NG	LEAK		14	POWER WINDOW (L FRONT)	OK	NG	NONE
3	ENGINE OIL LEVEL	OK	NG	DIRT		15	POWER WINDOW (R REAR)	OK	NG	NONE
4	OIL LEAKING	OK	NG	SMALL	BIG	16	POWER WINDOW (L REAR)	OK	NG	NONE
5	TIRE (R FRONT)	OK	NG	6.00/ R15	RFT	17	A/C CONDITION	OK	NG	WIND BLOWS OK CAN'T OPERATE NONE
6	TIRE (L FRONT)	OK	NG	6.00/ R15	RFT	18	INTERIOR CONDITION	OK	NG	DIRT SMOKING SMELL OTHER SMELL
7	TIRE (R REAR)	OK	NG	5.00/ R12	RFT	19	CHECK / WARNING LAMP	OK	E/G	ABS AIRBAG OTHER
8	TIRE (L REAR)	OK	NG	5.00/ R12	RFT	(COMMENT) A/C NONE				TESTER CHECK
9	ENGINE NOISE	OK	NG	E/G	OTHERS					
10	ENGINE CONDITION	OK	NG	IDLING	SMOKE					
11	EXHAUST LEAK	OK	NG	MUFFLER RUSTY	MISSING PARTS					
12	TRANSMISSION (AT / MT)	OK	NG	SHOCK	NOISE SLIP					
OPTION										
RADIO										
(注意) オプション品が付いていて作動するのは「○」、付いていて作動しないものは「×」、オプション品が付いていないものは「無印」でお願いします。						(注意) NGが入った項目は、窓ガラスに記載せずコメントにすべて記載をお願いします。オークションシートをチェックして、U3・B3以上の凹みキズ、フロントガラスの割れやヒビ(マーカで囲んで)、その他目立つ破損部分があった場合は、写真撮影をお願いします。				

YARD	神戸六甲(GL 神菱港運)
------	---------------

INSPECTER	シモン
-----------	-----

AA SHEET	✓
----------	---