

CONDITION CHECK REPORT

No.	BG510946	CHASSIS No.	KM70-0004760	DATE	2019 / 09 / 10
-----	----------	-------------	--------------	------	----------------

No.	Item	Status	Sub-Item	Value	Unit	Direction	Item	Status	Status	Status	Status	Status		
1	TIMING BELT CHANGE	YES			KM	13	POWER WINDOW (R FRONT)	OK	NG			NONE		
2	COOLANT LEVEL	OK	LEAK			14	POWER WINDOW (L FRONT)	OK	NG			NONE		
3	ENGINE OIL LEVEL	OK	DIRT			15	POWER WINDOW (R REAR)	OK	NG			NONE		
4	OIL LEAKING	OK	SMALL	BIG		16	POWER WINDOW (L REAR)	OK	NG			NONE		
5	TIRE (R FRONT)	OK	165 / 80 R 13	RFT		17	A/C CONDITION	OK	NG	WIND BLOWS OK	CAN'T OPERATE	A/C NONE		
6	TIRE (L FRONT)	OK	165 / 80 R 13	RFT		18	INTERIOR CONDITION	OK	NG	DIRT	SMOKING SMELL	OTHER SMELL		
7	TIRE (R REAR)	OK	225 / 50 R 12.5	RFT		19	CHECK / WARNING LAMP	OK	E/G	ABS	AIRBAG	OTHER		
8	TIRE (L REAR)	OK	225 / 50 R 12.5	RFT		(COMMENT) OIL LEAKING: NG : SMALL オイルしみ(ボディ) ラジオ電源入らず。 シート破れ。 ハンドルハゲ。 天張りうき。						TESTER CHECK		
9	ENGINE NOISE	OK	E/G	OTHERS										
10	ENGINE CONDITION	OK	IDLING	SMOKE										
11	EXHAUST LEAK	OK	MUFFLER RUSTY	MISSING PARTS										
12	TRANSMISSION (AT / MT)	OK	SHOCK	NOISE	SLIP									
OPTION														
RADIO	C D	DVD	SUN ROOF	FLIP DOWN MONITOR										
REAR MONITOR	BACK CAMERA	CRUISE CONTROL	POWER SLIDING DOOR (LEFT)	POWER SLIDING DOOR (RIGHT)										
POWER BACK DOOR														
(注意) オプション品が付いていて作動するものは「○」、付いていて作動しないものは「×」、オプション品が付いていないものは「無印」でお願いします。						(注意) NGが入った項目は、窓ガラスに記載せずコメントにすべて記載をお願いします。 オークションシートをチェックして、U3・B3以上の凹みキズ、フロントガラスの割れやヒビ(マーカーで囲んで)、その他目立つ破損部分があった場合は、写真撮影をお願いします。								

YARD	藤原A C 第3	INSPECTER	fudano	AA SHEET	○
------	----------	-----------	--------	----------	---