

CONDITION CHECK REPORT

BG No. B9517845	CHASSIS No. GHEFP - 203480	DATE 2019 / 9 / 17
------------------------	-----------------------------------	---------------------------

1	TIMING BELT CHANGE	YES		KM	13	POWER WINDOW (R FRONT)	(OK)	NG			NONE		
2	COOLANT LEVEL	(OK)	NG	LEAK		14	POWER WINDOW (L FRONT)	(OK)	NG		NONE		
3	ENGINE OIL LEVEL	(OK)	NG	DIRT		15	POWER WINDOW (R REAR)	(OK)	NG		NONE		
4	OIL LEAKING	(OK)	NG	SMALL	BIG	16	POWER WINDOW (L REAR)	(OK)	NG		NONE		
5	TIRE (R FRONT)	(OK)	NG	205/60 R6		RFT	17	A/C CONDITION	(OK)	NG	WIND BLOWS OK	CAN'T OPERATE	A/C NONE
6	TIRE (L FRONT)	(OK)	NG	/	R	RFT	18	INTERIOR CONDITION	OK	(NG)	(DIRT)	SMOKING SMELL	OTHER SMELL
7	TIRE (R REAR)	(OK)	NG	/	R	RFT	19	CHECK / WARNING LAMP	(OK)	E/G	ABS	AIRBAG	OTHER
8	TIRE (L REAR)	(OK)	NG	/	R	RFT	(COMMENT) <div style="font-size: 2em; font-weight: bold; text-align: center;"> ★キーレス ★純正7ア7" </div>					TESTER CHECK	
9	ENGINE NOISE	(OK)	NG	E/G	OTHERS								
10	ENGINE CONDITION	(OK)	NG	IDLING	SMOKE								
11	EXHAUST LEAK	(OK)	NG	MUFFLER RUSTY	MISSING PARTS								
12	TRANSMISSION (A) / MT)	(OK)	NG	SHOCK	NOISE	SLIP							
OPTION													
(RADIO)		(CD)		DVD		SUN ROOF		FLIP DOWN MONITOR					
REAR MONITOR		BACK CAMERA		CRUISE CONTROL		POWER SLIDING DOOR (LEFT)		POWER SLIDING DOOR (RIGHT)					
POWER BACK DOOR													
(注意) オプション品が付いていて作動するものは「O」、付いていて作動しないものは「×」、オプション品が付いていないものは「無印」でお願いします。													
(注意) NGが入った項目は、窓ガラスに記載せずコメントにすべて記載をお願いします。オークションシートをチェックして、U3・B3以上の凹みキズ、フロントガラスの割れやヒビ(マーカーで囲んで)、その他目立つ破損部分があった場合は、写真撮影をお願いします。													

YARD	ECL木更津	INSPECTER	A-U	AA SHEET	Q
------	--------	-----------	-----	----------	---