

CONDITION CHECK REPORT

BG No. <u>BC7520283</u>	CHASSIS No. <u>WDD2120272A683598</u>	DATE 2019 / <u>9</u> / <u>19</u>
-------------------------	--------------------------------------	----------------------------------

1	TIMING BELT CHANGE		YES	KM	13	POWER WINDOW (R FRONT)	(OK)	NG			NONE		
2	COOLANT LEVEL	(OK)	NG	LEAK		14	POWER WINDOW (L FRONT)	(OK)	NG		NONE		
3	ENGINE OIL LEVEL	(OK)	NG	DIRT		15	POWER WINDOW (R REAR)	(OK)	NG		NONE		
4	OIL LEAKING	(OK)	NG	SMALL	BIG	16	POWER WINDOW (L REAR)	(OK)	NG		NONE		
5	TIRE (R FRONT)	(OK)	NG	<u>245 45 R17</u>	(RFT)	17	A/C CONDITION	(OK)	NG	WIND BLOWS OK	CAN'T OPERATE	A/C NONE	
6	TIRE (L FRONT)	(OK)	NG		(RFT)	18	INTERIOR CONDITION	OK	(NG)	(DIRT)	SMOKING SMELL	OTHER SMELL	
7	TIRE (R REAR)	(OK)	NG		(RFT)	19	CHECK / WARNING LAMP	(OK)	E/G	ABS	AIRBAG	OTHER	
8	TIRE (L REAR)	(OK)	NG		(RFT)	(COMMENT) 1107-シート 7=セグ シート C-ター (8) 天板の T=子み					TESTER CHECK		
9	ENGINE NOISE	(OK)	NG	E/G	OTHERS								
10	ENGINE CONDITION	(OK)	NG	IDLING	SMOKE								
11	EXHAUST LEAK	(OK)	NG	MUFFLER RUSTY	MISSING PARTS								
12	TRANSMISSION (AT/MT)	(OK)	NG	SHOCK	NOISE						SLIP		
OPTION													
(RADIO)	(G.D)	DVD	SUN ROOF	FLIP DOWN MONITOR									
REAR MONITOR	BACK CAMERA	CRUISE CONTROL	POWER SLIDING DOOR (LEFT)	POWER SLIDING DOOR (RIGHT)									
POWER BACK DOOR													
(注意) オプション品が付いていて作動するものは「○」、付いていて作動しないものは「×」、オプション品が付いていないものは「無印」でお願いします。													
(注意) NGが入った項目は、窓ガラスに記載せずコメントにすべて記載をお願いします。オークションシートをチェックして、U3・B3以上の凹みキズ、フロントガラスの割れやヒビ(マーカで囲んで)、その他目立つ破損部分があった場合は、写真撮影をお願いします。													

YARD	ECL富津
------	-------

INSPECTER	泉
-----------	---

AA SHEET	0
----------	---