

CONDITION CHECK REPORT

BF No.	BG525181	CHASSIS No.	JHMCP36709C202965			
1	CORROSION CONDITION (Less than)	0% 	25%	50%	75%	100%
2	Holes	NO 	YES			
3	Broken	NO 	YES			
4	Engine	OK 	NG			
5	Brake System	OK 	NG			
6	Heater	OK 	NG			
7	Power Window	OK 	NG			
8	Transmission	OK 	NG			
9	A/C	OK 	NG			
10	Audio System	OK 	NG			
11	4WD Working	OK	NG	NONE 		
<p>(Comment) Hi dear The warning light is on. ABS , VSA</p> <p>You need to check the ABS. The other warning light out when the ABS check is complete.</p>						
<div style="display: flex; justify-content: space-between;"> UPDATE 2019/09/18 ver 1.0 </div>						