

CONDITION CHECK REPORT

No.	BG553162	CHASSIS No.	NCP50-0119602	DATE	2019 / 10 / 16
-----	----------	-------------	---------------	------	----------------

No.	Item	Status	Remarks	Item	Status	Remarks	Item	Status	Remarks	
1	TIMING BELT CHANGE	YES		KM	13	POWER WINDOW (R FRONT)	OK	NG	NONE	
2	COOLANT LEVEL	OK	NG	LEAK		14 POWER WINDOW (L FRONT)	OK	NG	NONE	
3	ENGINE OIL LEVEL	OK	NG	DIRT		15 POWER WINDOW (R REAR)	OK	NG	NONE	
4	OIL LEAKING	OK	NG	SMALL	BIG	16 POWER WINDOW (L REAR)	OK	NG	NONE	
5	TIRE (R FRONT)	OK	NG	165 / 80 R 13	RFT	17 A/C CONDITION	OK	NG	WIND BLOWS OK CAN'T OPERATE A/C NONE	
6	TIRE (L FRONT)	OK	NG	165 / 80 R 13	RFT	18 INTERIOR CONDITION	OK	NG	DIRT SMOKING SMELL OTHER SMELL	
7	TIRE (R REAR)	OK	NG	165 / 80 R 13	RFT	19 CHECK / WARNING LAMP	OK	E/G	ABS AIRBAG OTHER	
8	TIRE (L REAR)	OK	NG	165 / 80 R 13	RFT	(COMMENT) INTERIOR: NG : DIRT 天張りキズ ダッシュ糊跡 ハンドルシフトノブスレ コンソールキズ 荷室内キズ シート汚れ 室内汚れ 飛び石			TESTER CHECK	
9	ENGINE NOISE	OK	NG	E/G	OTHERS					
10	ENGINE CONDITION	OK	NG	IDLING	SMOKE					
11	EXHAUST LEAK	OK	NG	MUFFLER RUSTY	MISSING PARTS					
12	TRANSMISSION (AT / MT)	OK	NG	SHOCK	NOISE SLIP					
OPTION										
RADIO	C D	DVD	SUN ROOF	FLIP DOWN MONITOR						
REAR MONITOR	BACK CAMERA	CRUISE CONTROL	POWER SLIDING DOOR (LEFT)	POWER SLIDING DOOR (RIGHT)						
POWER BACK DOOR										
(注意) オプション品が付いていて作動するのは「○」、付いていて作動しないものは「×」、オプション品が付いていないものは「無印」でお願いします。					(注意) NGが入った項目は、窓ガラスに記載せずコメントにすべて記載をお願いします。 オークションシートをチェックして、U3・B3以上の凹みキズ、フロントガラスの割れやヒビ(マーカで囲んで)、その他目立つ破損部分があった場合は、写真撮影をお願いします。					

YARD	藤原AC第3
------	--------

INSPECTER	nyokai
-----------	--------

AA SHEET	○
----------	---