

CONDITION CHECK REPORT

BF No.	BG562093	CHASSIS No.	BU72-0006180	DATE	2019 / 10 / 18
--------	----------	-------------	--------------	------	----------------

1	TIMING BELT CHANGE		YES		KM	13	POWER WINDOW (R FRONT)	OK	NG				NONE
2	COOLANT LEVEL	OK	NG	LEAK			14 POWER WINDOW (L FRONT)	OK	NG				NONE
3	ENGINE OIL LEVEL	OK	NG	DIRT			15 POWER WINDOW (R REAR)	OK	NG				NONE
4	OIL LEAKING	OK	NG	SMALL	BIG		16 POWER WINDOW (L REAR)	OK	NG				NONE
5	TIRE (R FRONT)	OK	NG	195/80R15		RFT	17 A/C CONDITION	OK	NG	WIND BLOWS OK	CAN'T OPERATE		NONE
6	TIRE (L FRONT)	OK	NG	195/80R15		RFT	18 INTERIOR CONDITION	OK	NG	DIRT	SMOKING SMELL	OTHER SMELL	
7	TIRE (R REAR)	OK	NG	195/80R15		RFT	19 CHECK / WARNING LAMP	OK	E/G	ABS	AIRBAG	OTHER	
8	TIRE (L REAR)	OK	NG	195/80R15		RFT	(COMMENT) RADIO FAILURE KEY FAILURE A/C NONE					TESTER CHECK	
9	ENGINE NOISE	OK	NG	E/G	OTHERS								
10	ENGINE CONDITION	OK	NG	IDLING	SMOKE								
11	EXHAUST LEAK	OK	NG	MUFFLER RUSTY	MISSING PARTS								
12	TRANSMISSION (AT / MT)	OK	NG	SHOCK	NOISE	SLIP							
OPTION													
RADIO													
(注意) オプション品が付いていて作動するのは「○」、付いていて作動しないものは「×」、オプション品が付いていないものは「無印」でお願いします。													

YARD	木更津・畑沢第2ヤード(SPX)
------	------------------

INSPECTER	渡邊
-----------	----

AA SHEET	✓
----------	---