

CONDITION CHECK REPORT

BF No.	BG569390	CHASSIS No.	BZ11-32B213
--------	----------	-------------	-------------

DATE 2019 / 10 / 24

1	TIMING BELT CHANGE	YES		KM	13	POWER WINDOW (R FRONT)	OK	NG			NONE	
2	COOLANT LEVEL	OK	NG	LEAK		14	POWER WINDOW (L FRONT)	OK	NG		NONE	
3	ENGINE OIL LEVEL	OK	NG	DIRT		15	POWER WINDOW (R REAR)	OK	NG		NONE	
4	OIL LEAKING	OK	NG	SMALL	BIG	16	POWER WINDOW (L REAR)	OK	NG		NONE	
5	TIRE (R FRONT)	OK	NG	175/65 R 14	RFT	17	A/G CONDITION	OK	NG	WIND BLOWS OK	CAN'T OPERATE	A/G NONE
6	TIRE (L FRONT)	OK	NG	175/65 R 14	RFT	18	INTERIOR CONDITION	OK	NG	DIRT	SMOKING SMELL	OTHER SMELL
7	TIRE (R REAR)	OK	NG	175/65 R 14	RFT	19	CHECK / WARNING LAMP	OK	E/G	ABS	AIRBAG	OTHER
9	TIRE (L REAR)	OK	NG	175/65 R 14	RFT	(COMMENT) 天張りシミ、オイル 各シートカバー、ヨレ 室内ヨレ					TESTER CHECK	
9	ENGINE NOISE	OK	NG	E/G	OTHERS							
10	ENGINE CONDITION	OK	NG	IDLING	SMOKE							
11	EXHAUST LEAK	OK	NG	MUFFLER RUSTY	MISSING PARTS							
12	TRANSMISSION (AT / MT)	OK	NG	SHOCK	NOISE						SLIP	
OPTION												
RADIO		G-D		DVD		SUN ROOF		FLIP DOWN MONITOR				
REAR MONITOR		BACK CAMERA		CRUISE CONTROL		POWER SLIDING DOOR (LEFT)		POWER SLIDING DOOR (RIGHT)				
POWER BACK DOOR												
(注意) オプション品が付いていて作動するものは「○」、付いていて作動しないものは「×」、オプション品が付いていないものは「無印」でお願いします。												
(注意) NGが入った項目は、窓ガラスに記載せずコメントにすべて記載をお願いします。オプションシートをチェックして、U3・B3以上の凹みキズ、フロントガラスの割れやビビ(マーカで囲んで)、その他目立つ破損部分があった場合は、写真撮影をお願いします。												

YARD ナガセ自動車株式会社

INSPECTER 尾根音也

AA SHEET