

## CONDITION CHECK REPORT

BF No.	BG574284	CHASSIS No.	KANA[42]113385KANA	DATE	2019 / 10 / 29
--------	----------	-------------	--------------------	------	----------------

1	TIMING BELT CHANGE		YES		KM	13	POWER WINDOW (R FRONT)	OK	NG			NONE	
2	COOLANT LEVEL	OK	NG	LEAK			14 POWER WINDOW (L FRONT)	OK	NG			NONE	
3	ENGINE OIL LEVEL	OK	NG	DIRT			15 POWER WINDOW (R REAR)	OK	NG			NONE	
4	OIL LEAKING	OK	NG	SMALL	BIG		16 POWER WINDOW (L REAR)	OK	NG			NONE	
5	TIRE (R FRONT)	OK	NG	285/75R16	RFT		17 A/C CONDITION	OK	NG	WIND BLOWS OK	CAN'T OPERATE	NONE	
6	TIRE (L FRONT)	OK	NG	285/75R16	RFT		18 INTERIOR CONDITION	OK	NG	DIRT	SMOKING SMELL	OTHER SMELL	
7	TIRE (R REAR)	OK	NG	285/75R16	RFT		19 CHECK / WARNING LAMP	OK	E/G	ABS	AIRBAG	OTHER	
8	TIRE (L REAR)	OK	NG	285/75R16	RFT		(COMMENT) BONNET DAMPER FAILURE ODOMETER FAILURE OIL LEAKING SMALL CHECK LAMP ON				TESTER CHECK		✓
9	ENGINE NOISE	OK	NG	E/G	OTHERS								
10	ENGINE CONDITION	OK	NG	IDLING	SMOKE								
11	EXHAUST LEAK	OK	NG	MUFFLER RUSTY	MISSING PARTS								
12	TRANSMISSION ((AT) / MT)	OK	NG	SHOCK	NOISE	SLIP							
OPTION													
RADIO		C D		DVD		SUN ROOF							
		BACK CAMERA		CRUISE CONTROL									
(注意) オプション品が付いていて作動するのは「○」、付いていて作動しないものは「×」、オプション品が付いていないものは「無印」でお願いします。													

YARD	神戸港島(GL 新日本トランス)
------	------------------

INSPECTER	島田
-----------	----

AA SHEET	✓
----------	---