

CONDITION CHECK REPORT

BG No. <u>PC7574253</u>	CHASSIS No. <u>TRJ150-0068312</u>	DATE <u>2019/10/30</u>
-------------------------	-----------------------------------	------------------------

No.	Item	Status	Tire			13	14	15	16	17	18	19								
			Size	Side	Pressure							Check	Warning	Lamp	ABS	Airbag	Other			
1	TIMING BELT CHANGE	YES				POWER WINDOW (R FRONT)	OK	NG						NONE						
2	COOLANT LEVEL	OK	LEAK			POWER WINDOW (L FRONT)	OK	NG						NONE						
3	ENGINE OIL LEVEL	OK	DIRT			POWER WINDOW (R REAR)	OK	NG						NONE						
4	OIL LEAKING	OK	SMALL	BIG		POWER WINDOW (L REAR)	OK	NG						NONE						
5	TIRE (R FRONT)	OK	<u>265/65R17</u>	RFT		A/C CONDITION	OK	NG	WIND BLOWS OK	CAN'T OPERATE	A/C NONE									
6	TIRE (L FRONT)	OK		R	RFT	INTERIOR CONDITION	OK	NG	DIRT	SMOKING SMELL	OTHER SMELL									
7	TIRE (R REAR)	OK		R	RFT	CHECK / WARNING LAMP	OK	E/G	ABS	AIRBAG	OTHER									
8	TIRE (L REAR)	OK		R	RFT	(COMMENT) 小物交換のため 木更津 左・右フロントピストン						TESTER CHECK								
9	ENGINE NOISE	OK	E/G	OTHERS																
10	ENGINE CONDITION	OK	IDLING	SMOKE																
11	EXHAUST LEAK	OK	MUFFLER RUSTY	MISSING PARTS																
12	TRANSMISSION (AT/MT)	OK	SHOCK	NOISE	SLIP															
OPTION																				
RADIO	C D	DVD	SUN ROOF	FLIP DOWN MONITOR																
REAR MONITOR	BACK CAMERA	CRUISE CONTROL	POWER SLIDING DOOR (LEFT)	POWER SLIDING DOOR (RIGHT)																
POWER BACK DOOR																				
(注意) オプション品が付いていて作動するものは「○」、付いていて作動しないものは「×」、オプション品が付いていないものは「無印」でお願いします。						(注意) NGが入った項目は、窓ガラスに記載せずコメントにすべて記載をお願いします。オークションシートをチェックして、U3・B3以上の凹みキズ、フロントガラスの割れやヒビ(マーカーで囲んで)、その他目立つ破損部分があった場合は、写真撮影をお願いします。														

YARD	ECL木更津	INSPECTER	木更津	AA SHEET	2
------	--------	-----------	-----	----------	---