

CONDITION CHECK REPORT

No.	BG595701	CHASSIS No.	U71T-0001363					DATE	2019 / 11 / 11				
1	TIMING BELT CHANGE		YES			KM	13	POWER WINDOW (R FRONT)	OK	NG			○ NONE
2	COOLANT LEVEL	○	NG	LEAK			14	POWER WINDOW (L FRONT)	OK	NG			○ NONE
3	ENGINE OIL LEVEL	○	NG	DIRT			15	POWER WINDOW (R REAR)	OK	NG			○ NONE
4	OIL LEAKING	○	NG	SMALL	BIG		16	POWER WINDOW (L REAR)	OK	NG			○ NONE
5	TIRE (R FRONT)	○	NG	145 / 80 R 12	RFT		17	A/C CONDITION	OK	○ NG	WIND BLOWS OK	CAN'T OPERATE	○ A/C NONE
6	TIRE (L FRONT)	○	NG	145 / 80 R 12	RFT		18	INTERIOR CONDITION	OK	○ NG	○ DIRT	SMOKING SMELL	OTHER SMELL
7	TIRE (R REAR)	○	NG	145 / 80 R 12	RFT		19	CHECK / WARNING LAMP	○ OK	E/G	ABS	AIRBAG	OTHER
8	TIRE (L REAR)	○	NG	145 / 80 R 12	RFT		(COMMENT) AC: NG : NONE INTERIOR: NG : DIRT 天張り汚れたるみ ハンドルハゲ シフトノブスレ シート破れ大 車内汚れ大 CD読み込まず 飛び石					TESTER CHECK	
9	ENGINE NOISE	○	NG	E/G	OTHERS								
10	ENGINE CONDITION	○	NG	IDLING	SMOKE								
11	EXHAUST LEAK	○	NG	MUFFLER RUSTY	MISSING PARTS								
12	TRANSMISSION (AT / MT)	○	NG	SHOCK	NOISE SLIP								
OPTION													
○ RADIO	× CD	DVD	SUN ROOF	FLIP DOWN MONITOR									
REAR MONITOR	BACK CAMERA	CRUISE CONTROL	POWER SLIDING DOOR (LEFT)	POWER SLIDING DOOR (RIGHT)									
POWER BACK DOOR													
(注意) オプション品が付いていて作動するものは「○」、付いていて作動しないものは「×」、オプション品が付いていないものは「無印」でお願いします。													
(注意) NGが入った項目は、窓ガラスに記載せずコメントにすべて記載をお願いします。 オークションシートをチェックして、U3・B3以上の凹みキズ、フロントガラスの割れやヒビ(マーカーで囲んで)、その他目立つ破損部分があった場合は、写真撮影をお願いします。													

YARD	藤原AC第3
------	--------

INSPECTER	nyokai
-----------	--------

AA SHEET	○
----------	---