

CONDITION CHECK REPORT

BF No.	B6 598330	CHASSIS No.	AcA38-5233763	DATE	2019 / 11 / 12
--------	-----------	-------------	---------------	------	----------------

1	TIMING BELT CHANGE		YES		KM	13	POWER WINDOW (R FRONT)	<input checked="" type="checkbox"/>	NG			NONE
2	COOLANT LEVEL	<input checked="" type="checkbox"/>	NG	LEAK			14 POWER WINDOW (L FRONT)	<input checked="" type="checkbox"/>	NG			NONE
3	ENGINE OIL LEVEL	<input checked="" type="checkbox"/>	NG	DIRT			15 POWER WINDOW (R REAR)	<input checked="" type="checkbox"/>	NG			NONE
4	OIL LEAKING	<input checked="" type="checkbox"/>	NG	SMALL	BIG		16 POWER WINDOW (L REAR)	<input checked="" type="checkbox"/>	NG			NONE
5	TIRE (R FRONT)	<input checked="" type="checkbox"/>	NG	225/65 R17		RFT	17 A/C CONDITION	<input checked="" type="checkbox"/>	NG	WIND BLOWS OK	CAN'T OPERATE	A/C NONE
6	TIRE (L FRONT)	<input checked="" type="checkbox"/>	NG	225/65 R17		RFT	18 INTERIOR CONDITION	<input checked="" type="checkbox"/>	NG	DIRT	SMOKING SMELL	OTHER SMELL
7	TIRE (R REAR)	<input checked="" type="checkbox"/>	NG	225/65 R17		RFT	19 CHECK / WARNING LAMP	<input checked="" type="checkbox"/>	E/G	ABS	AIRBAG	OTHER
8	TIRE (L REAR)	<input checked="" type="checkbox"/>	NG	225/65 R17		RFT	(COMMENT)					TESTER CHECK
9	ENGINE NOISE	<input checked="" type="checkbox"/>	NG	E/G	OTHERS							
10	ENGINE CONDITION	<input checked="" type="checkbox"/>	NG	IDLING	SMOKE							
11	EXHAUST LEAK	<input checked="" type="checkbox"/>	NG	MUFFLER RUSTY	MISSING PARTS							
12	TRANSMISSION (ATV/MT)	<input checked="" type="checkbox"/>	NG	SHOCK	NOISE	SLIP						
OPTION												
<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	SUN ROOF		FLIP DOWN MONITOR							
REAR MONITOR	BACK CAMERA	CRUISE CONTROL	POWER SLIDING DOOR (LEFT)		POWER SLIDING DOOR (RIGHT)							
POWER BACK DOOR												
(注意) オプション品が付いていて作動するのは「○」、付いていて作動しないものは「×」、オプション品が付いていないものは「無印」でお願いします。							(注意) NGが入った項目は、窓ガラスに記載せずコメントにすべて記載をお願いします。オークションシートをチェックして、U3・B3以上の凹みキズ、フロントガラスの割れやヒビ(マーカーで囲んで)、その他目立つ破損部分があった場合は、写真撮影をお願いします。					

YARD	
------	--

INSPECTER	子子
-----------	----

AA SHEET	9
----------	---