

# CONDITION CHECK REPORT

DATE 2017/11/14

BF No. BG602870 CHASSIS No. VJY12-019315

1 TIMING BELT CHANGE	YES			KM	13	POWER WINDOW (R FRONT)	OK	NG			NONE
2 COOLANT LEVEL	OK	NG	LEAK			POWER WINDOW (L FRONT)	OK	NG			NONE
3 ENGINE OIL LEVEL	OK	NG	DIRT			POWER WINDOW (R REAR)	OK	NG			NONE
4 OIL LEAKING	OK	NG	SMALL BIG			POWER WINDOW (L REAR)	OK	NG			NONE
5 TIRE (R FRONT)	OK	NG	165' R13	RFT		A/C CONDITION	OK	NG	WIND BLOWS OK	CAN'T OPERATE	A/G NONE
6 TIRE (L FRONT)	OK	NG	/ R	RFT		INTERIOR CONDITION	OK	NG	DIRT	SMOKING SMELL	OTHER SMELL
7 TIRE (R REAR)	OK	NG	/ R	RFT		19 CHECK / WARNING LAMP	OK	E/G	ABS	AIRBAG	OTHER
8 TIRE (L REAR)	OK	NG	/ R	RFT		(COMMENT)			TESTER CHECK		
9 ENGINE NOISE	OK	NG	E/G OTHERS								
10 ENGINE CONDITION	OK	NG	IDLING SMOKE								
11 EXHAUST LEAK	OK	NG	MUFFLER RUSTY MISSING PARTS								
12 TRANSMISSION (AT / MT)	OK	NG	SHOCK NOISE	SLIP							

OPTION

RADIO REAR MONITOR POWER BACK DOOR	CD BACK CAMERA	DVD CRUISE CONTROL	SUN ROOF POWER SLIDING DOOR (LEFT)	FLIP DOWN MONITOR POWER SLIDING DOOR (RIGHT)
--	-------------------	-----------------------	---------------------------------------	---

(注意) オプション品が付いていて作動するのは「○」、付いていて作動しないものは「×」、オプション品が付いていないものは「無印」でお願いします。

(注意) NGが入った項目は、窓ガラスに記載せずコメントにすべて記載お願します。オプションシートをチェックして、U3・B3以上の凹みキズ、フロントガラスの割れやヒビ(マーカ-で開く)、その他目立つ破損部分があった場合は、写真撮影お願します。

YARD 博多箱崎ヤード

INSPECTOR ジノ

AA SHEET 78L