

CONDITION CHECK REPORT

BG No. 619666

CHASSIS No.

EE107-0028252

DATE

20<sup>19</sup> / 11 / 26

1	TIMING BELT CHANGE	YES			13	POWER WINDOW (R FRONT)	OK	NG		NONE
2	COOLANT LEVEL	OK	NG	LEAK	14	POWER WINDOW (L FRONT)	OK	NG		NONE
3	ENGINE OIL LEVEL	OK	NG	DIRT	15	POWER WINDOW (R REAR)	OK	NG		NONE
4	OIL LEAKING	OK	NG	SMALL EIG	16	POWER WINDOW (L REAR)	OK	NG		NONE
5	TIRE (R FRONT)	OK	NG	155/155R13 RFT	17	AIR CONDITION	OK	NG	WIND FLOWS OK	NONE
6	TIRE (L FRONT)	OK	NG	/ R RFT	18	INTERIOR CONDITION	OK	NG	DIRT SMOKING SMELL OTHER SMELL	
7	TIRE (R REAR)	OK	NG	/ R RFT	19	CHECK / WARNING LAMP	OK	E/G	ABS AIRBAG OTHER	
8	TIRE (L REAR)	OK	NG	/ R RFT	(COMMENT) ・天張り・汚水 ・ラジオ・不良 ・エアコン冷えず					
9	ENGINE NOISE	OK	NG	E/G OTHERS						
10	ENGINE CONDITION	OK	NG	IDLING SMOKE						
11	EXHAUST LEAK	OK	NG	MUFFLER RUSTY MISSING PARTS						
12	TRANSMISSION (AT MT)	OK	NG	SHOCK NOISE SLIP						
OPTION <del>RADIO</del> CD DVD SUN ROOF FLIP DOWN MONITOR REAR MONITOR BACK CAMERA CRUISE CONTROL POWER SLIDING DOOR (LEFT) POWER SLIDING DOOR (RIGHT) POWER BACK DOOR										
(注意) オプション品が付いていて作動するものは「O」、付いていて作動しないものは「X」、オプション品が付いていないものは「無印」でお願いします。					(注意) NGが入った項目は、窓ガラスに記載せずコメントにすべて記載をお願いします。 オークションシートをチェックして、U3・B3以上の凹みキズ、フロントガラスの割れやヒビ(マーカークラック)、その他目立つ傷損部分があった場合は、写真撮影をお願いします。					

Yard

ECL新門司

Inspector

KK

AA SHEET

