

CONDITION CHECK REPORT

BF No.	BG628265	CHASSIS No.	ZNE10-0350989	DATE	2019 / 12 / 3
--------	----------	-------------	---------------	------	---------------

1	TIMING BELT CHANGE		YES		KM	13	POWER WINDOW (R FRONT)	OK	NG			NONE			
2	COOLANT LEVEL	OK	NG	LEAK			14 POWER WINDOW (L FRONT)	OK	NG			NONE			
3	ENGINE OIL LEVEL	OK	NG	DIRT			15 POWER WINDOW (R REAR)	OK	NG			NONE			
4	OIL LEAKING	OK	NG	SMALL	BIG		16 POWER WINDOW (L REAR)	OK	NG			NONE			
5	TIRE (R FRONT)	OK	NG	195/65R15		RFT	17 A/C CONDITION	OK	NG	WIND BLOWS OK	CAN'T OPERATE	NONE			
6	TIRE (L FRONT)	OK	NG	195/65R15		RFT	18 INTERIOR CONDITION	OK	NG	DIRT	SMOKING SMELL	OTHER SMELL			
7	TIRE (R REAR)	OK	NG	195/65R15		RFT	19 CHECK / WARNING LAMP	OK	E/G	ABS	AIRBAG	OTHER			
8	TIRE (L REAR)	OK	NG	195/65R15		RFT	(COMMENT) CHECK LAMP ON CAN NOT OPEN TRANK IDLING FAILURE				TESTER CHECK				
9	ENGINE NOISE	OK	NG	E/G	OTHERS										
10	ENGINE CONDITION	OK	NG	IDLING	SMOKE										
11	EXHAUST LEAK	OK	NG	MUFFLER RUSTY	MISSING PARTS										
12	TRANSMISSION ((AT) / MT)	OK	NG	SHOCK	NOISE	SLIP									
OPTION															
	RADIO	C D	DVD												

(注意) オプション品が付いていて作動するのは「○」、付いていて作動しないものは「×」、オプション品が付いていないものは「無印」でお願いします。
 (注意) NGが入った項目は、窓ガラスに記載せずコメントにすべて記載をお願いします。オークションシートをチェックして、U3・B3以上の凹みキズ、フロントガラスの割れやヒビ(マーカーで囲んで)、その他目立つ破損部分があった場合は、写真撮影をお願いします。

YARD	長州出島(リアル下関海陸)
------	---------------

INSPECTER	大城
-----------	----

AA SHEET	✓
----------	---