

# CONDITION CHECK REPORT

BG No.	716336	CHASSIS No.	CW5W - 0009397
--------	--------	-------------	----------------

DATE **20.20** / 1 / 20

1	TIMING BELT CHANGE		YES		KM	13	POWER WINDOW (R FRONT)	OK	NG				NONE	
2	COOLANT LEVEL	OK	NG	LEAK			14 POWER WINDOW (L FRONT)	OK	NG				NONE	
3	ENGINE OIL LEVEL	OK	NG	DIRT			15 POWER WINDOW (R REAR)	OK	NG				NONE	
4	OIL LEAKING	OK	NG	SMALL	BIG		16 POWER WINDOW (L REAR)	OK	NG				NONE	
5	TIRE (R FRONT)	OK	NG	225/55 R18		RFT	17 A/C CONDITION	OK	NG	WIND BLOWS OK	CAN'T OPERATE	A/C NONE		
6	TIRE (L FRONT)	OK	NG			R	18 INTERIOR CONDITION	OK	NG	DIRT	SMOKING SMELL	OTHER SMELL		
7	TIRE (R REAR)	OK	NG			R	19 CHECK / WARNING LAMP	OK	E/G	ABS	AIRBAG	OTHER		
8	TIRE (L REAR)	OK	NG			R	(COMMENT)  <div style="font-size: 1.5em; font-family: cursive;">                     スタートキー                      ハットビルズト                 </div>					TESTER CHECK		
9	ENGINE NOISE	OK	NG	E/G	OTHERS									
10	ENGINE CONDITION	OK	NG	IDLING	SMOKE									
11	EXHAUST LEAK	OK	NG	MUFFLER RUSTY	MISSING PARTS									
12	TRANSMISSION (AT/MT)	OK	NG	SHOCK	NOISE	SLIP								
OPTION														
	RADIO	CD		DVD	SUN ROOF	FLIP DOWN MONITOR								
	REAR MONITOR	BACK CAMERA		CRUISE CONTROL	POWER SLIDING DOOR (LEFT)	POWER SLIDING DOOR (RIGHT)								
	POWER BACK DOOR													
(注意) オプション品が付いていて作動するものは「○」、付いていて作動しないものは「×」、オプション品が付いていないものは「無印」をお願いします。							(注意) NGが入った項目は、窓ガラスに記載せずコメントにすべて記載をお願いします。オークションシートをチェックして、U3・B3以上の凹みキズ、フロントガラスの割れやヒビ(マーカーで囲んで)、その他目立つ破損部分があった場合は、写真撮影をお願いします。							

YARD	ECL木更津
------	--------

INSPECTER	カサハシ
-----------	------

AA SHEET	9
----------	---