

## CONDITION CHECK REPORT

BF No.	BG805935	CHASSIS No.	TRH200-0111536	DATE	2020 / 1 / 23
--------	----------	-------------	----------------	------	---------------

1	TIMING BELT CHANGE		YES		KM	13	POWER WINDOW (R FRONT)	<input checked="" type="radio"/>	NG			NONE	
2	COOLANT LEVEL	<input checked="" type="radio"/>	NG	LEAK			14	POWER WINDOW (L FRONT)	<input checked="" type="radio"/>	NG		NONE	
3	ENGINE OIL LEVEL	<input checked="" type="radio"/>	NG	DIRT			15	POWER WINDOW (R REAR)	<input checked="" type="radio"/>	NG		NONE	
4	OIL LEAKING	<input checked="" type="radio"/>	NG	SMALL	BIG		16	POWER WINDOW (L REAR)	<input checked="" type="radio"/>	NG		NONE	
5	TIRE (R FRONT)	<input checked="" type="radio"/>	NG	185/75R15		RFT	17	A/C CONDITION	<input checked="" type="radio"/>	NG	WIND BLOWS OK	CAN'T OPERATE	NONE
6	TIRE (L FRONT)	<input checked="" type="radio"/>	NG	185/75R15		RFT	18	INTERIOR CONDITION	<input checked="" type="radio"/>	NG	DIRT	SMOKING SMELL	OTHER SMELL
7	TIRE (R REAR)	<input checked="" type="radio"/>	NG	185/75R15		RFT	19	CHECK / WARNING LAMP	<input checked="" type="radio"/>	E/G	ABS	AIRBAG	OTHER
8	TIRE (L REAR)	<input checked="" type="radio"/>	NG	185/75R15		RFT	(COMMENT) ALL TIRE WORN     (注意) NGが入った項目は、窓ガラスに記載せずコメントにすべて記載をお願いします。 オークションシートをチェックして、U3・B3以上の凹みキズ、フロントガラスの割れやヒビ(マーカーで囲んで)、その他目立つ破損部分があった場合は、写真撮影をお願いします。				TESTER CHECK		
9	ENGINE NOISE	<input checked="" type="radio"/>	NG	E/G	OTHERS								
10	ENGINE CONDITION	<input checked="" type="radio"/>	NG	IDLING	SMOKE								
11	EXHAUST LEAK	<input checked="" type="radio"/>	NG	MUFFLER RUSTY	MISSING PARTS								
12	TRANSMISSION (AT / MT)	<input checked="" type="radio"/>	NG	SHOCK	NOISE	SLIP							
OPTION													
	<input checked="" type="radio"/>												

YARD	長州出島(リアル下関海陸)	INSPECTER	大城	AA SHEET	<input checked="" type="checkbox"/>
------	---------------	-----------	----	----------	-------------------------------------