

CONDITION CHECK REPORT

No.	BG807445	CHASSIS No.	FE51CBT-550955			DATE	2020 / 01 / 27		
-----	----------	-------------	----------------	--	--	------	----------------	--	--

1	TIMING BELT CHANGE		YES		KM	13	POWER WINDOW (R FRONT)	OK	NG				NONE
2	COOLANT LEVEL	OK	NG	LEAK			14 POWER WINDOW (L FRONT)	OK	NG				NONE
3	ENGINE OIL LEVEL	OK	NG	DIRT			15 POWER WINDOW (R REAR)	OK	NG				NONE
4	OIL LEAKING	OK	NG	SMALL	BIG		16 POWER WINDOW (L REAR)	OK	NG				NONE
5	TIRE (R FRONT)	OK	NG	185 / 85 R 16	RFT		17 A/C CONDITION	OK	NG	WIND BLOWS OK	CAN'T OPERATE	A/C NONE	
6	TIRE (L FRONT)	OK	NG	185 / 85 R 16	RFT		18 INTERIOR CONDITION	OK	NG	DIRT	SMOKING SMELL	OTHER SMELL	
7	TIRE (R REAR)	OK	NG	165 / 8 R 14	RFT		19 CHECK / WARNING LAMP	OK	E/G	ABS	AIRBAG	OTHER	
8	TIRE (L REAR)	OK	NG	165 / 8 R 14	RFT		(COMMENT) OIL LEAKING: NG : SMALL INTERIOR: NG : DIRT エンジン下部オイルにじみ 天張り汚れキズ ハンドルシフトノブハゲ大 ダッシュキズ ドア内張り汚れ シート破れ大 室内汚れ中 飛び石			TESTER CHECK			
9	ENGINE NOISE	OK	NG	E/G	OTHERS								
10	ENGINE CONDITION	OK	NG	IDLING	SMOKE								
11	EXHAUST LEAK	OK	NG	MUFFLER RUSTY	MISSING PARTS								
12	TRANSMISSION (AT / MT)	OK	NG	SHOCK	NOISE	SLIP							

OPTION				
RADIO	C D	DVD	SUN ROOF	FLIP DOWN MONITOR
REAR MONITOR	BACK CAMERA	CRUISE CONTROL	POWER SLIDING DOOR (LEFT)	POWER SLIDING DOOR (RIGHT)
POWER BACK DOOR				

(注意) オプション品が付いていて作動するものは「○」、付いていて作動しないものは「×」、オプション品が付いていないものは「無印」でお願いします。

(注意) NGが入った項目は、窓ガラスに記載せずコメントにすべて記載をお願いします。オークションシートをチェックして、U3・B3以上の凹みキズ、フロントガラスの割れやヒビ(マーカーで囲んで)、その他目立つ破損部分があった場合は、写真撮影をお願いします。

YARD	藤原AC第3	INSPECTER	nyokai	AA SHEET	○
------	--------	-----------	--------	----------	---