

CONDITION CHECK REPORT

BF No.	BG811132	CHASSIS No.	KZH106-0027990
--------	----------	-------------	----------------

DATE 2020 / /

1	TIMING BELT CHANGE		YES		100,092 KM	13	POWER WINDOW (R FRONT)		OK	NG			NONE	
2	COOLANT LEVEL		OK	NG	LEAK		14	POWER WINDOW (L FRONT)	OK	NG			NONE	
3	ENGINE OIL LEVEL		OK	NG	DIRT		15	POWER WINDOW (R REAR)	OK	NG			NONE	
4	OIL LEAKING		OK	NG	SMALL	BIG	16	POWER WINDOW (L REAR)	OK	NG			NONE	
5	TIRE (R FRONT)		OK	NG	215/70 R15	RFT	17	A/C CONDITION	OK	NG	WIND BLOWS OK	GAN'T OPERATE	A/C NONE	
6	TIRE (L FRONT)		OK	NG	215/70 R15	RFT	18	INTERIOR CONDITION	OK	NG	DIRT	SMOKING SMELL	OTHER SMELL	
7	TIRE (R REAR)		OK	NG	215/70 R15	RFT	19	CHECK / WARNING LAMP	OK	E/G	ABS	AIRBAG	OTHER	
8	TIRE (L REAR)		OK	NG	215/70 R15	RFT	(COMMENT) 天張り加工 コンソール加工 ルーレ内張り、キズ、コゲ、動物の毛 下廻りサビ、フロッグ						TESTER CHECK	
9	ENGINE NOISE		OK	NG	E/G	OTHERS								
10	ENGINE CONDITION		OK	NG	IDLING	SMOKE								
11	EXHAUST LEAK		OK	NG	MUFFLER RUSTY	MISSING PARTS								
12	TRANSMISSION (AT/MT)		OK	NG	SHOCK	NOISE							SLIP	
OPTION														
RADIO		C D		DVD		SUN ROOF		FLIP DOWN MONITOR						
REAR MONITOR		BACK CAMERA		CRUISE CONTROL		POWER SLIDING DOOR (LEFT)		POWER SLIDING DOOR (RIGHT)						
POWER BACK DOOR														
(注意) オプション品が付いていて作動するものは「○」、付いていて作動しないものは「×」、オプション品が付いていないものは「無印」でお願いします。														
(注意) NGが入った項目は、窓ガラスに記載せずコメントにすべて記載をお願いします。オークションシートをチェックして、U3・B3以上の凹みキズ、フロントガラスの割れやヒビ(マーカーで囲んで)、その他目立つ故障部分があった場合は、写真撮影をお願いします。														

YARD	ナガセ自動車株式会社
------	------------

INSPECTER	萩原
-----------	----

AA SHEET	
----------	--