

CONDITION CHECK REPORT

BG No. **828734** CHASSIS No. **ZC32S-103197**

DATE 20^年 / 2 / 13

1 TIMING BELT CHANGE	YES			13 POWER WINDOW (R FRONT)	OK	NG	NONE
2 COOLANT LEVEL	OK	NG	LEAK	14 POWER WINDOW (L FRONT)	OK	NG	NONE
3 ENGINE OIL LEVEL	OK	NG	DIRT	15 POWER WINDOW (R REAR)	OK	NG	NONE
4 OIL LEAKING	OK	NG	SMALL BIG	16 POWER WINDOW (L REAR)	OK	NG	NONE
5 TIRE (R FRONT)	OK	NG	195 / 45 R 17 RFT	17 AIR CONDITION	OK	NG	WIND BLOWS OK NONE
6 TIRE (L FRONT)	OK	NG	/ RFT	18 INTERIOR CONDITION	OK	NG	DIRT SMOKING OTHER SMELL SMELL
7 TIRE (R REAR)	OK	NG	/ RFT	19 CHECK / WARNING LAMP	OK	E/G	ABS AIRBAG OTHER
8 TIRE (L REAR)	OK	NG	/ RFT	(COMMENT) (DVD: NG OK ・工具等L・スリッパ等			
9 ENGINE NOISE	OK	NG	E/G OTHERS				
10 ENGINE CONDITION	OK	NG	IDLING SMOKE				
11 EXHAUST LEAK	OK	NG	MUFFLER MISSING RUSTY PARTS				
12 TRANSMISSION (AT MT)	OK	NG	SHOCK NOISE SLIP				

OPTION

RADIO (O) CD (O) DVD (O) SUN ROOF FLIP DOWN MONITOR

REAR MONITOR BACK CAMERA CRUISE CONTROL POWER SLIDING DOOR (LEFT) POWER SLIDING DOOR (RIGHT)

POWER BACK DOOR

(注意) オプション品が付いていて作動するものは「O」、付いていて作動しないものは「×」、オプション品が付いていないものは「無印」でお願いします。

(注意) NGが入った項目は、窓ガラスに記載をコメントにすべて記載をお願いします。オークションシートをチェックして、U3・B3以上の凹みキズ、フロントガラスの割れやヒビ(マーカーで囲んで)、その注目立つ箇所部分があった場合は、写真撮影をお願いします。

Yard **ECL 新門司** Inspector **KK2** AA SHEET