

CONDITION CHECK REPORT

BF No.	BG956157	CHASSIS No.	TRJ 120-5016286	DATE	2020 / 3 / 16
--------	----------	-------------	-----------------	------	---------------

1	TIMING BELT CHANGE	YES		KM	13	POWER WINDOW (R FRONT)	(OK)	NG			NONE	
2	COOLANT LEVEL	(OK)	NG		14	POWER WINDOW (L FRONT)	(OK)	NG			NONE	
3	ENGINE OIL LEVEL	(OK)	NG		15	POWER WINDOW (R REAR)	(OK)	NG			NONE	
4	OIL LEAKING	(OK)	NG	SMALL		16	POWER WINDOW (L REAR)	(OK)	NG		NONE	
5	TIRE (R FRONT)	(OK)	NG	265/65 R17	RFT	17	A/C CONDITION	(OK)	NG	WIND BLOWS OK	CAN'T OPERATE	A/C NONE
6	TIRE (L FRONT)	(OK)	NG	265/65 R17	RFT	18	INTERIOR CONDITION	(OK)	NG	DIRT	SMOKING SMELL	OTHER SMELL
7	TIRE (R REAR)	(OK)	NG	265/65 R17	RFT	19	CHECK / WARNING LAMP	(OK)	E/G	ABS	AIRBAG	OTHER
8	TIRE (L REAR)	(OK)	NG	265/65 R17	RFT	(COMMENT)					TESTER CHECK	
9	ENGINE NOISE	(OK)	NG	E/G	OTHERS							
10	ENGINE CONDITION	(OK)	NG	IDLING	SMOKE							
11	EXHAUST LEAK	(OK)	NG	MUFFLER RUSTY	MISSING PARTS							
12	TRANSMISSION (AT / MT)	(OK)	NG	SHOCK	NOISE							
OPTION												
(RADIO)		(CD)		(DVD)		(SUN ROOF)		FLIP DOWN MONITOR				
REAR MONITOR		BACK CAMERA		CRUISE CONTROL		POWER SLIDING DOOR (LEFT)		POWER SLIDING DOOR (RIGHT)				
POWER BACK DOOR												
<p>(注意) オプション品が付いていて作動するのは「O」、付いていて作動しないものは「×」、オプション品が付いていないものは「無印」でお願いします。</p> <p>(注意) NGが入った項目は、窓ガラスに記載せずコメントにすべて記載をお願いします。オークションシートをチェックして、U3・B3以上の凹みキズ、フロントガラスの割れやヒビ(マーカで囲んで)、その他目立つ破損部分があった場合は、写真撮影をお願いします。</p>												

YARD	KANDA
------	-------

INSPECTER	柳 詰
-----------	-----

AA SHEET	Q
----------	---