

# CONDITION CHECK REPORT

BF No.	BH158520	CHASSIS No.	N2T260-3044589	DATE	2020 / 3 23
--------	----------	-------------	----------------	------	-------------

1	TIMING BELT CHANGE	YES		KM	13	POWER WINDOW (R FRONT)	(OK)	NG				NONE	
2	COOLANT LEVEL	(OK)	NG	LEAK		14	POWER WINDOW (L FRONT)	(OK)	NG			NONE	
3	ENGINE OIL LEVEL	(OK)	NG	DIRT		15	POWER WINDOW (R REAR)	(OK)	NG			NONE	
4	OIL LEAKING	(OK)	NG	SMALL	BIG	16	POWER WINDOW (L REAR)	(OK)	NG			NONE	
5	TIRE (R FRONT)	(OK)	NG	185/70 R14	RFT	17	A/C CONDITION	(OK)	NG	WIND BLOWS OK	CAN'T OPERATE	A/C NONE	
6	TIRE (L FRONT)	(OK)	NG	185/70 R14	RFT	18	INTERIOR CONDITION	(OK)	NG	DIRT	SMOKING SMELL	OTHER SMELL	
7	TIRE (R REAR)	(OK)	NG	185/70 R14	RFT	19	CHECK / WARNING LAMP	(OK)	E/G	ABS	AIRBAG	OTHER	
8	TIRE (L REAR)	(OK)	NG	185/70 R14	RFT	(COMMENT)					TESTER CHECK		
9	ENGINE NOISE	(OK)	NG	E/G	OTHERS								
10	ENGINE CONDITION	(OK)	NG	IDLING	SMOKE								
11	EXHAUST LEAK	(OK)	NG	MUFFLER RUSTY	MISSING PARTS								
12	TRANSMISSION (AT/MT)	(OK)	NG	SHOCK	NOISE								SLIP
OPTION													
(RADIO)	(CD)	(DVD)	SUN ROOF	FLIP DOWN MONITOR									
REAR MONITOR	BACK CAMERA	CRUISE CONTROL	POWER SLIDING DOOR (LEFT)	POWER SLIDING DOOR (RIGHT)									
POWER BACK DOOR													
(注意) オプション品が付いていて作動するのは「O」、付いていて作動しないものは「×」、オプション品が付いていないものは「無印」でお願いします。						(注意) NGが入った項目は、窓ガラスに記載せずコメントにすべて記載をお願いします。オークションシートをチェックして、U3・B3以上の凹みキズ、フロントガラスの割れやヒビ(マーカで囲んで)、その他目立つ破損部分があった場合は、写真撮影をお願いします。							

YARD	KANDA	INSPECTER	柳 詰	AA SHEET
------	-------	-----------	-----	----------