

CONDITION CHECK REPORT

| | | | | | |
|--------|-----------|-------------|-----------------------------------|------|---------------|
| BF No. | BH 160637 | CHASSIS No. | ACA38- 5252962 5252962 | DATE | 2020 / 3 / 21 |
|--------|-----------|-------------|-----------------------------------|------|---------------|

| | | | | | | | | | | | | | |
|-----------------|------------------------|----------------|---------------------------|----------------------------|------------------------|------------------------|------|-----|---------------|---------------|-------------|--|------|
| 1 | TIMING BELT CHANGE | YES | KM | 13 | POWER WINDOW (R FRONT) | (OK) | NG | | | NONE | | | |
| 2 | COOLANT LEVEL | (OK) | LEAK | | 14 | POWER WINDOW (L FRONT) | (OK) | NG | | NONE | | | |
| 3 | ENGINE OIL LEVEL | (OK) | DIRT | | 15 | POWER WINDOW (R REAR) | (OK) | NG | | NONE | | | |
| 4 | OIL LEAKING | (OK) | SMALL BIG | | 16 | POWER WINDOW (L REAR) | (OK) | NG | | NONE | | | |
| 5 | TIRE (R FRONT) | (OK) | 235/55 R/18 | RFT | 17 | A/C CONDITION | (OK) | NG | WIND BLOWS OK | CAN'T OPERATE | A/C NONE | | |
| 6 | TIRE (L FRONT) | (OK) | 235/55 R/18 | RFT | 18 | INTERIOR CONDITION | (OK) | NG | DIRT | SMOKING SMELL | OTHER SMELL | | |
| 7 | TIRE (R REAR) | (OK) | 235/55 R/18 | RFT | 19 | CHECK / WARNING LAMP | (OK) | E/G | ABS | AIRBAG | OTHER | | |
| 8 | TIRE (L REAR) | (OK) | 235/55 R/18 | RFT | (COMMENT) | | | | | TESTER CHECK | | | |
| 9 | ENGINE NOISE | (OK) | E/G | OTHERS | | | | | | | | | |
| 10 | ENGINE CONDITION | (OK) | IDLING | SMOKE | | | | | | | | | |
| 11 | EXHAUST LEAK | (OK) | MUFFLER RUSTY | MISSING PARTS | | | | | | | | | |
| 12 | TRANSMISSION (AT / MT) | (OK) | SHOCK | NOISE | | | | | | | | | SLIP |
| OPTION | | | | | | | | | | | | | |
| RADIO | C D | DVD | SUN ROOF | FLIP DOWN MONITOR | | | | | | | | | |
| REAR MONITOR | BACK CAMERA | CRUISE CONTROL | POWER SLIDING DOOR (LEFT) | POWER SLIDING DOOR (RIGHT) | | | | | | | | | |
| POWER BACK DOOR | | | | | | | | | | | | | |

(注意) オプション品が付いていて作動するのは「O」、付いていて作動しないものは「×」、オプション品が付いていないものは「無印」でお願いします。

(注意) NGが入った項目は、窓ガラスに記載せずコメントにすべて記載をお願いします。オークションシートをチェックして、U3・B3以上の凹みキズ、フロントガラスの割れやヒビ(マーカで囲んで)、その他目立つ破損部分があった場合は、写真撮影をお願いします。

| | | | | |
|------|-------|-----------|-----|----------|
| YARD | KANDA | INSPECTER | 柳 詰 | AA SHEET |
|------|-------|-----------|-----|----------|