

## CONDITION CHECK REPORT

No.	BH160453	CHASSIS No.	TRH200-0031613	DATE	2020 / 03 / 21
-----	----------	-------------	----------------	------	----------------

1	TIMING BELT CHANGE		YES		KM	13	POWER WINDOW (R FRONT)	<input checked="" type="radio"/> OK	NG				NONE
2	COOLANT LEVEL	<input checked="" type="radio"/> OK	NG	LEAK			14 POWER WINDOW (L FRONT)	<input checked="" type="radio"/> OK	NG				NONE
3	ENGINE OIL LEVEL	<input checked="" type="radio"/> OK	NG	DIRT			15 POWER WINDOW (R REAR)	OK	NG				<input checked="" type="radio"/> NONE
4	OIL LEAKING	<input checked="" type="radio"/> OK	NG	SMALL	BIG		16 POWER WINDOW (L REAR)	OK	NG				<input checked="" type="radio"/> NONE
5	TIRE (R FRONT)	<input checked="" type="radio"/> OK	NG	195 / 80 R 15	RFT		17 A/C CONDITION	<input checked="" type="radio"/> OK	NG		WIND BLOWS OK	CAN'T OPERATE	A/C NONE
6	TIRE (L FRONT)	<input checked="" type="radio"/> OK	NG	195 / 80 R 15	RFT		18 INTERIOR CONDITION	OK	<input checked="" type="radio"/> NG		<input checked="" type="radio"/> DIRT	SMOKING SMELL	OTHER SMELL
7	TIRE (R REAR)	<input checked="" type="radio"/> OK	NG	195 / 80 R 15	RFT		19 CHECK / WARNING LAMP	<input checked="" type="radio"/> OK	E/G		ABS	AIRBAG	OTHER
8	TIRE (L REAR)	<input checked="" type="radio"/> OK	NG	195 / 80 R 15	RFT		(COMMENT) INTERIOR: NG : DIRT  シート破れ小					TESTER CHECK	
9	ENGINE NOISE	<input checked="" type="radio"/> OK	NG	E/G	OTHERS								
10	ENGINE CONDITION	<input checked="" type="radio"/> OK	NG	IDLING	SMOKE								
11	EXHAUST LEAK	<input checked="" type="radio"/> OK	NG	MUFFLER RUSTY	MISSING PARTS								
12	TRANSMISSION (AT / MT)	<input checked="" type="radio"/> OK	NG	SHOCK	NOISE	SLIP							
OPTION													
<input checked="" type="radio"/> RADIO	C D	DVD	SUN ROOF	FLIP DOWN MONITOR									
REAR MONITOR	BACK CAMERA	CRUISE CONTROL	POWER SLIDING DOOR (LEFT)	POWER SLIDING DOOR (RIGHT)									
POWER BACK DOOR													
(注意) オプション品が付いていて作動するものは「○」、付いていて作動しないものは「×」、オプション品が付いていないものは「無印」でお願いします。													
(注意) NGが入った項目は、窓ガラスに記載せずコメントにすべて記載をお願いします。オークションシートをチェックして、U3・B3以上の凹みキズ、フロントガラスの割れやヒビ(マーカーで囲んで)、その他目立つ破損部分があった場合は、写真撮影をお願いします。													

YARD	藤原AC第3
------	--------

INSPECTER	aikawa
-----------	--------

AA SHEET	<input checked="" type="radio"/>
----------	----------------------------------